

July 18, 2024

Michelle Dando, Community Association Manager Legacy Southwest Property Management, LLC 8668 John Hickman Pkwy Ste. 801 Frisco, TX 75034

Via Email: michelle@legacysouthwestpm.com

Property: The Shops at Prestonwood

2725 Creekway Drive, Carrollton, 75010

Service: RESERVE STUDY

Project No.: C240308-2 Attachment:Report

Dear Michelle and Members of the Board,

Criterium-Dotson Engineers has completed a Reserve Study Update for The Shops at Prestonwood Townhomes. Enclosed is our report for your review.

This Reserve Study has been performed in general accordance with Community Association Institute (CAI) National Reserve Study Standards.

Our report should be reviewed in its entirety, including its Appendices which contain the financial analysis, captioned photographs, and reference documents.

Criterium-Dotson Engineers appreciates this opportunity to assist Legacy Southwest Property Management, LLC, in support of the The Shops at PrestonwoodAssociation's facility and financial planning.

Thank you.
Criterium-Dotson Engineers
David Dotson
David Dotson President

The Shops at Prestonwood Reserve Study

The Shops at Prestonwood 2725 Creekway Drive Carrollton , TX 75010

Prepared for:

Legacy Southwest Property Management

The Shops at Prestonwood

6010 W. Spring Creek Parkway

Plano, Texas 75024

Prepared By: Summer Megdadi, RS



1402 S Custer, Suite 1004, McKinney, TX 75072 972-562-1011





Table of Contents

INTRODUCTION	6
EXECUTIVE SUMMARY	7
PURPOSE & SCOPE	9
PHYSICAL ANALYSIS	11
FINANCIAL ANALYSIS	22
LIMITATIONS	25
CONCLUSION	26
APPENDICES	27
APPENDIX A - FINANCIAL EXHIBITS	28
INFORMATION, ASSUMPTIONS, & DATA	29
30-YEAR CASH-FLOW PROJECTIONS - SUMMARY GRAPH	
CASH-FLOW PROJECTION AT THE CURRENT FUNDING LEVEL	32
ALTERNATIVE 1 FUNDING PLAN	34
ALTERNATIVE 2 FUNDING PLAN	36
ALTERNATIVE 3 FUNDING PLAN	38
CURRENT RESERVE ITEMS & EXPENDITURE PLANNING	40
ANNUAL RESERVE EXPENDITURE BUDGET PROJECTION	45
Upcoming Expenditures in Years 1 and 2	57
RESERVE EXPENDITURE BUDGET PROJECTION SUMMARY	59
APPENDIX B - PHOTOGRAPHS	61
COMPONENT DETAILS	62
**COMPONENT DETAILS (NEW)	127
APPENDIX C - REFERENCE DOCUMENTS	193
NATIONAL RESERVE STUDY STANDARDS	194
TERMS OF REFERENCE RESERVE STUDY	200



1.0 INTRODUCTION

Following authorization by the 's Board of Directors, Criterium-Dotson Engineers has conducted a Reserve Study Update of your 381 unit residential community located at 2725 Creekway Drive in Carrollton, TX. Our work is consistent with our proposal dated 03/08/2024.

This report must be reviewed in its entirety to understand our findings and their limitations. The Appendices are an integral part of this report and must be included in any review. Please refer to Appendix C for definitions of common terms of reference used herein.

We have conducted the study in general accordance with the National Reserve Study Standards published by the Community Association Institute (CAI). Please refer to Appendix C which contains a copy of the CAI standard.

This study was conducted by licensed Professional Engineers and other qualified staff working under the responsible charge of a CAI-certified Reserve Specialist.

Summer Megdadi prepared this report and the attached financial analysis. This report is principally based on our visual site inspection on April 16, 2024.

David Dotson, PE, RS, of Criterium-Dotson Engineers reviewed their findings.

Criterium presents this confidential report for the Board's review and use.

In reviewing the engineering assumptions, cost estimates and projected fund values herein, please understand that their accuracy diminishes as time passes. Long range facility maintenance projections are intended only to indicate the likely pattern of reserve expenditures and to guide financial planning.

Criterium agrees with CAI's recommendation that reserve studies should be updated regularly to allow periodic adjustment of facility plans and funding strategies.

Powered by HomeRun IQ Page 6 of 204

2.0 EXECUTIVE SUMMARY

In summary, as a result of our on-site inspections and other investigations, we find the common components of the property to be in fair general condition and well-maintained.

We have identified an inventory of Association-responsible common components which are likely to require periodic repair or replacement or other recurrent reserve investment.

We have formed an opinion of the remaining useful life of each component. We have estimated the current cost of required reserve expenditures for their repair or replacement. We have projected annual reserve budgets over a 30-year planning period.

In summary, the 30-year total of projected reserve expenditures, (current dollar cost estimates inflated at 4.00% annually), is \$20,660,247. The average annual expenditures for the 30-year period is \$688,675.

The Shops at Prestonwood Townhomes Association has provided us with information on the Association's Reserve Fund and the current funding plan. Our initial financial analysis was based on the data supplied.

Our projections indicate that the current reserve fund contributions will not be adequate.



	Current Funding Levels	Alternative 1, Level Funding with Steps	Alternative 2, Escalating Funding	Alternative 3, Escalating Funding with Special Assessments
ASSOCIATION				
Starting Balance	\$1,380,770	\$1,380,770	\$1,380,770	\$1,380,770
Contributions (30-Year Total)	\$6,730,192	\$25,350,000	\$29,123,963	\$6,730,192
Additional Capital	\$0	\$0	\$0	\$0
Interest / Returns (30-Year Total)	\$126,615	\$1,625,777	\$1,915,922	\$311,156
Expenditures (30-Year Total)	\$20,660,247	\$20,660,247	\$20,660,247	\$20,660,247
Ending Balance	(\$12,422,670)	\$7,696,299	\$11,760,407	\$761,871
OWNER				
Starting Contributions (/unit/year)	\$315	\$1,050	\$919	\$315
Total Special Assessments Amount	\$0	\$0	\$0	\$13,000,000

Powered by HomeRun IQ Page 8 of 204

3.0 PURPOSE & SCOPE

3.1. OBJECTIVES

The purpose of this reserve study is to determine a reserve needs plan for the Association, to evaluate the current rate of contribution to the reserve fund, and, if required, to suggest alternate funding strategies.

This report is intended to be used as a tool by the Association's Board for considering and managing its future financial obligations, for determining appropriate reserve fund allocations, and for informing the individual Owners of the Association's required reserve expenditures and the resulting financial plan.

For purposes of financial planning, Association-responsible expenses are typically divided into two categories:

- Operation and maintenance (O&M) of commonly-held elements of real property and other assets. These O&M expenses usually include taxes, insurance, property management costs and other service
- Reserve expenditures for major periodic repairs or replacement of commonly-held elements.

Long-term reserve expenditures, the funding plan and ensuring adequate Reserve Fund balances are the focus of this Reserve Study.

History demonstrates that, as time progresses, property conditions and management strategies will change. As a result, planned scopes of work may be altered or deferred. Actual cost in the marketplace will vary from estimates. Actual rates of inflation and returns on investment will vary from projections.

For these reasons, we concur with the Community Association Institute guidelines and recommend that this reserve study be updated every three to five years.

3.2. LEVEL OF SERVICE

The Community Association Institute (CAI) identifies four levels of service for Reserve Studies:

- 1. Full Reserve Study
- 2. Reserve Study Update, With Site Visit/On-Site Review
- 3. Reserve Study Update, No-Site-Visit/Off Site Review
- 4. Preliminary Reserve Study, Community Not Yet Constructed

All may be appropriate for a community, depending on the condition of the facility and the phase of their planning cycle. The CAI National Reserve Study Standard in Appendix C contains more detail on these levels of service and the scope of study of each of them.

Our current study is a Level II - Reserve Study Update with On-Site Analysis.

Criterium's actual scope of service is enhanced and exceeds the CAI standard in the Amount principal ways:

- Our investigation and evaluation of the property is performed by experienced professional engineers
- After preparing and submitting our initial analysis, we engage in collaborative review process with the Board, toward developing a financial plan more responsive to the needs of the The Shops at Prestonwood.

Powered by HomeRun IQ Page 9 of 204

3.3. SOURCES OF INFORMATION

The following people were interviewed during our study:
• Michelle Dando, Community Association Manager - Legacy Southwest Property Management

The following documents were provided to us and reviewed:

• The Shops at Prestonwood Reserve Study 2017



Powered by HomeRun IQ Page 10 of 204

4.0 PHYSICAL ANALYSIS

4.1 PROPERTY DESCRIPTION

Please refer to the Appendices for captioned photographs.

The Shops at Prestonwood is a 381-unit residential community located on a 25 acre site, at 2725 Creekway Drive in Carrollton , TX.

The Shops at Prestonwood was constructed beginning in 2008. The community currently consists of thirty-seven two and three-story buildings, common areas, and an amenity center equipped with a pool. The buildings occupy an estimated twenty five acre parcel of sloping ground. Each building houses between three and nine residential units. There are currently a total of 381 units on the property.

4.2 COMMON COMPONENTS

Grouped by Category

CATEGORY

COMPONENT	NEXT REPL	EXPECTED USEFUL LIFE	REMAINING USEFUL LIFE	COST PER MEASURE	QUANTITY	CURRENT COST
Amenities						
Amenity Center Furniture Replacement	01/01/ 2030	20:00	5:06	\$10,560.00	1 Lot	\$10,560
BBQ Grill Replacement	01/01/ 2025	15:00	0:06	\$1,585.00	2 Ea	\$3,170
Decking Repairs - Creekway (Periodic)	01/01/ 2026	10:00	1:06	\$24.00	355 SF	\$8,520
Decking Repairs - Riverview (Periodic)	01/01/ 2030	10:00	5:06	\$24.00	355 SF	\$8,520
Exercise Equipment - Elliptical Replacement	01/01/ 2026	14:00	1:06	\$5,940.00	2 Ea	\$11,880
Exercise Equipment - Spinner Replacement	01/01/ 2026	14:00	1:06	\$1,610.00	2 Ea	\$3,220
Exercise Equipment - Treadmill Replacement	01/01/ 2026	14:00	1:06	\$7,788.00	3 Ea	\$23,364

Grand Total \$7,150,422

Powered by HomeRun IQ Page 11 of 204

Powered by HomeRun IQ

COMPONENT	NEXT REPL	EXPECTED USEFUL LIFE	REMAINING USEFUL LIFE	COST PER MEASURE	QUANTITY	CURREN COS
Exercise Equipment - Weight Machine Replacement	01/01/ 2026	14:00	1:06	\$5,940.00	1 Ea	\$5,94
Flat Screen Television Replacement	01/01/ 2026	10:00	1:06	\$1,848.00	2 Ea	\$3,69
Mailbox Replacement	01/01/ 2038	30:00	13:06	\$1,980.00	24 Ea	\$47,52
Park Bench Replacement	01/01/ 2033	25:00	8:06	\$1,060.00	4 Ea	\$4,24
Pool Coping to Decking Joint, Both Pools (Deck-O-Seal)	01/01/ 2027	4:00	2:06	\$9.00	280 LF	\$2,52
Pool Coping/Tile Replacement - Creekway	01/01/ 2039	30:00	14:06	\$55.00	140 LF	\$7,70
Pool Coping/Tile Replacement - Riverview	01/01/ 2050	30:00	25:06	\$55.00	140 LF	\$7,70
Pool Fencing - Clean/Prime/Paint (Periodic) - Creekway	01/01/ 2025	8:00	0:06	\$12.25	395 LF	\$4,83
Pool Fencing - Clean/Prime/Paint (Periodic) - Riverview	01/01/ 2026	8:00	1:06	\$12.25	395 LF	\$4,83
Pool Fencing - Replacement	01/01/ 2049	40:00	24:06	\$80.00	790 LF	\$63,20
Pool Furniture Replacement	01/01/ 2028	7:00	3:06	\$12,000.00	1 Lot	\$12,00
Pool Re-Surface (Gunite) - Creekway	01/01/ 2027	10:00	2:06	\$11.00	1,050 SF	\$11,55
Pool Re-Surface (Gunite) - Riverview	01/01/ 2030	10:00	5:06	\$8.58	1,050 SF	\$9,00
Wood Arbor Replacement	01/01/ 2034	25:00	9:06	\$35.00	1,250 SF	\$43,75
menities Total						\$297,73
uilding Exterior						
Door Replacement	01/01/ 2034	25:00	9:06	\$924.00	9	\$8,31
rand Total						\$7,150,42

Page 12 of 204

NEXT REPL	EXPECTED USEFUL LIFE	REMAINING USEFUL LIFE	COST PER MEASURE	QUANTITY	CURREN
01/01/ 2025	8:00	0:06	\$462.00	255 Ea	\$117,81
01/01/ 2028	5:00	3:06	\$660.00	126 Ea	\$83,16
01/01/ 2026	10:00	1:06	\$22.00	2,028 LF	\$44,61
01/01/ 2027	10:00	2:06	\$9.00	2,738 LF	\$24,64
01/01/ 2049	40:00	24:06	\$60.00	2,738 LF	\$164,28
07/01/ 2024	8:00	0:00	\$1,200.00	381	\$457,20
01/01/ 2035	20:00	10:06	\$13,740.00	127 Ea	\$1,744,98
01/01/ 2038	20:00	13:06	\$13,740.00	127 Ea	\$1,744,98
01/01/ 2041	20:00	16:06	\$13,740.00	127 Ea	\$1,744,98
					\$6,134,9
01/01/ 2035	25:00	10:06	\$198.00	60	\$11,88
01/01/ 2025	15:00	0:06	\$6.50	540 SF	\$3,5
01/01/ 2029	20:00	4:06	\$9.00	705 SF	\$6,34
01/01/ 2026	8:00	1:06	\$11,000.00	1 Lot	\$11,00
01/01/ 2035	25:00	10:06	\$7,260.00	1 Lot	\$7,20
01/01/	30:00	14:06	\$990.00	3 Ea	\$2,9
	01/01/ 2025 01/01/ 2028 01/01/ 2026 01/01/ 2027 01/01/ 2049 07/01/ 2035 01/01/ 2038 01/01/ 2041 01/01/ 2041 01/01/ 2041	NEXT REPL USEFUL LIFE 01/01/ 2025 8:00 01/01/ 2028 5:00 01/01/ 2026 10:00 01/01/ 2027 10:00 01/01/ 2049 40:00 07/01/ 2024 8:00 01/01/ 2035 20:00 01/01/ 2038 20:00 01/01/ 2041 20:00 01/01/ 2035 25:00 01/01/ 2025 15:00 01/01/ 2026 8:00 01/01/ 2035 25:00	NEXT REPL USEFUL LIFE USEFUL LIFE 01/01/2025 8:00 0:06 01/01/2028 5:00 3:06 01/01/2026 10:00 1:06 01/01/2027 10:00 2:06 01/01/2049 40:00 24:06 07/01/2024 8:00 0:00 01/01/2035 20:00 10:06 01/01/2038 20:00 13:06 01/01/2041 20:00 16:06 01/01/2035 25:00 10:06 01/01/2025 15:00 0:06 01/01/2029 20:00 4:06 01/01/2026 8:00 1:06 01/01/2026 25:00 10:06	NEXT REPL USEFULLIFE USEFULLIFE MEASURE 01/01/ 2025 8:00 0:06 \$462.00 01/01/ 2028 5:00 3:06 \$660.00 01/01/ 2026 10:00 1:06 \$22.00 01/01/ 2027 10:00 2:06 \$9.00 01/01/ 2049 40:00 24:06 \$60.00 07/01/ 2024 8:00 0:00 \$1,200.00 01/01/ 2035 20:00 10:06 \$13,740.00 01/01/ 2038 20:00 16:06 \$13,740.00 01/01/ 2035 25:00 10:06 \$198.00 01/01/ 2025 15:00 0:06 \$6.50 01/01/ 2029 20:00 4:06 \$9.00 01/01/ 2026 8:00 1:06 \$11,000.00 01/01/ 2035 25:00 10:06 \$7,260.00	NEXT REPL USEFUL LIFE MEASURE QUANTITY 01/01/ 2025 8:00 0:06 \$462.00 255 Ea 01/01/ 2028 5:00 3:06 \$660.00 126 Ea 01/01/ 2026 10:00 1:06 \$22.00 2,028 LF 01/01/ 2027 10:00 2:06 \$9.00 2,738 LF 01/01/ 2049 40:00 24:06 \$60.00 2,738 LF 07/01/ 2024 8:00 0:00 \$1,200.00 381 01/01/ 2035 20:00 10:06 \$13,740.00 127 Ea 01/01/ 2038 20:00 16:06 \$13,740.00 127 Ea 01/01/ 2035 25:00 10:06 \$13,740.00 127 Ea 01/01/ 2025 15:00 0:06 \$6.50 540 SF 01/01/ 2029 20:00 4:06 \$9.00 705 SF 01/01/ 2026 8:00 1:06 \$11,000.00 1 Lot 01/01/ 2035 25:00 10:06 \$7,260.00 1 Lot

Powered by HomeRun IQ Page 13 of 204

COMPONENT	NEXT REPL	EXPECTED USEFUL LIFE	REMAINING USEFUL LIFE	COST PER MEASURE	QUANTITY	CURREN' COS
Building Interior Total						\$42,96
Mechanical						
Access Control System Replacement	07/01/ 2024	15:00	0:00	\$5,000.00	1 Ea	\$5,00
Ceiling Fan Replacement	01/01/ 2027	16:00	2:06	\$350.00	8 Ea	\$2,80
Drinking Fountain Replacement	01/01/ 2025	15:00	0:06	\$1,500.00	4 Ea	\$6,00
Electrical Panel Replacement	01/01/ 2049	40:00	24:06	\$2,775.00	3 Ea	\$8,32
HVAC Replacement	01/01/ 2037	15:00	12:06	\$9,600.00	2 Ea	\$19,20
Irrigation Controller Replacement	07/01/ 2024	12:00	0:00	\$990.00	22 Ea	\$21,78
Pond Equipment Replacement	01/01/ 2038	15:00	13:06	\$12,000.00	1 Lot	\$12,00
Pool Filter Replacement (Large)	01/01/ 2030	15:00	5:06	\$3,000.00	1 Ea	\$3,00
Pool Pump Replacement (2 HP)	01/01/ 2025	6:00	0:06	\$2,200.00	2 Ea	\$4,40
Surveillance Camera Replacement	01/01/ 2025	4:00	0:06	\$429.00	10 Ea	\$4,29
Surveillance Equipment Upgrade	01/01/ 2030	12:00	5:06	\$6,000.00	1 Lot	\$6,00
Mechanical Total						\$92,79
Other						
Reserve Study Updates	07/01/ 2028	4:00	4:00	\$5,800.00	1 Ea	\$5,80
Contingency	01/01/ 2025	1:00	0:06	\$30,000.00	1 Ea	\$30,00
						\$35,80

Powered by HomeRun IQ Page 14 of 204

CATEGORY

COMPONENT	NEXT REPL	EXPECTED USEFUL LIFE	REMAINING USEFUL LIFE	COST PER MEASURE	QUANTITY	CURREI CO:
e						
Brick Perimeter Fencing Repairs - Topped w/ Metal (Periodic)	01/01/ 2031	10:00	6:06	\$18.00	431 LF	\$7,7
Brick Perimeter Fencing Repairs - 6' (Periodic)	01/01/ 2027	10:00	2:06	\$22.00	1,024 LF	\$22,5
Brick Perimeter Fencing - Topped w/ Metal	01/01/ 2041	30:00	16:06	\$180.00	431 LF	\$77,5
Brick Perimeter Fencing - 6'	01/01/ 2041	30:00	16:06	\$220.00	1,024 LF	\$225,2
Concrete Parking Lot - Seal Joints, Stripe	01/01/ 2027	5:00	2:06	\$2,500.00	1 Lot	\$2,5
Concrete Walkway and Drive Repairs (Periodic)	01/01/ 2025	7:00	0:06	\$18.00	4,950 SF	\$89,1
Column Repairs	01/01/ 2026	10:00	1:06	\$280.00	14 Ea	\$3,9
Retaining Wall Repairs (~ 4')	01/01/ 2031	10:00	6:06	\$24,000.00	1 Lot	\$24,0
Wood Perimeter Fencing Replacement	01/01/ 2033	20:00	8:06	\$44.00	992 LF	\$43,6
Wood Perimeter Fencing Stain	01/01/ 2027	5:00	2:06	\$8.00	992 LF	\$7,9
Wrought Iron Fencing - 6' Clean/Prime/Paint (Periodic)	01/01/ 2028	10:00	3:06	\$12.25	305 LF	\$3,7
Wrought Iron Atop Brick Fence- Clean/Prime/ Paint (Periodic)	01/01/ 2028	10:00	3:06	\$5.50	431 LF	\$2,3
Wrought Iron Fencing Replacement - 6'	01/01/ 2049	40:00	24:06	\$75.00	305 LF	\$22,8
Wrought Iron Fencing Replacement Atop Brick Fence	01/01/ 2049	40:00	24:06	\$30.00	431 LF	\$12,9
e Total						\$546,1

Grand Total \$7,150,422

Powered by HomeRun IQ Page 15 of 204

4.3 CONDITION ASSESSMENT

4.3.1 Site Improvements

Description & Observations

The site slopes generally to the creek running through the middle of the site. A number of mortared stone retaining walls assist in creating suitable building pads for the structures. Stone retaining walls are in fair condition. Repairs were recently made. They will require periodic repairs on an approximate 10 year cycle. Any cracks that develop in the retaining walls should be sealed immediately to avoid further damage to the wall due to freeze / thaw cycles.

Drainage in the community is handled over the surface with curb inlets and underground storm drainage at the streets. Most storm drainage is conveyed to the municipal system. Some runoff is diverted to the pond north of the amenity center.

Community streets are owned and maintained by the City. There are a total of six striped parking areas located throughout the community. Parking lots are constructed of cast in place concrete.

Parking lot concrete is generally in fair condition. Restriping of the spaces will be necessary in the future. Any cracks in the concrete paving in the parking areas should be sealed to prevent seepage of water below the paving, causing premature failure. Periodic pavement patching, repairs, and replacement will also be required in the future. Sidewalks run throughout the community. With the exception of the common area flatwork, all sidewalks are owned and maintained by the City.

The concrete walkways in the common areas are in fair general condition at this time; they will require periodic repairs and replacement due to the expansive nature of soils in this area.

Landscaping on the site is well established. Most consists primarily of ornamental trees and shrubs throughout the property, with foundation plantings surrounding many of the building footprints. The east border of the property along Charles Street is lined with a combination of fencing materials that include metal fencing (~305 lin. ft.), brick fencing (~880 lin. ft.), and brick fencing topped with metal accents (~430 lin.ft.). A relatively short run of stained wood fencing is installed behind buildings 10 and 11 (~990 ln. ft.). Metal fencing is also located at the pool area (~400 lin. ft.). Privacy fencing is located behind many units and consists of either brick or metal. Landscaping on the site is typically maintained through a service contract with an outside servicing company. Seasonal lawn treatment and maintenance, annual plantings, and pruning should be addressed in a general operating budget. Brick perimeter fencing is approximately 16 years old.

Brick fencing will require periodic repairs on an approximate 10 year cycle beginning in about five years. Brick fences similar to this one typically last an average of thirty years in the area; therefore, we suggest that replacement of the brick perimeter fencing be planned for in approximately 14 years. Cleaning, priming, and painting of the metal fencing will be required approximately every 8 to 10 years. No issues were observed with the wood fencing along the alley behind buildings 10 and 11. Wood fences typically need replacement after 20 years of service. The privacy fencing in place at grade level at some units is also in generally fair condition. Maintenance will be required on these fences similar to those at the perimeter.

The current condition of the site improvements is consistent with the normal performance and aging of this system.

The remaining useful life is as expected.

No unusual conditions were noted.

Common Components & Required Reserve Expenditures

Powered by HomeRun IQ Page 16 of 204

Appendix A contains an inventory of all site improvements which are common components, and a detailed schedule of projected reserve expenditures for these items.

4.3.2 Building Structure and Exterior

Description & Observations

The amenity center and townhomes are of stick-framed construction with pitched roofs. Foundations are cast-in-place, post-tension concrete slabs. There did not appear to be any issues of concern regarding capital expenditures for the structural systems for the buildings or the amenity center at the time of the investigation. Trees and other vegetation are planted extremely close to unit foundations. This may lead to differential foundation movement in the future. Soils around the perimeters of the foundations should be monitored for dryness.

Townhome and amenity center attic ventilation is provided by roof hawk and soffit vents.

Although attic areas were not directly investigated, there was no reported history of problems regarding ventilation in these spaces. The quantity and location of vents appears to be adequate as viewed from street level.

Townhome and amenity center pitched roof surfaces are covered in asphalt shingles with woven valleys. There were no visible areas of exposed flashing to determine the material used for flashing. Roof surfacing is applied over roof sheathing. The main entrance into the amenity center is covered with a standing seam metal roofing. An aluminum gutter and downspout system that predominately discharges storm water directly to an underground conveyance is in place at most of the buildings.

No issues were observed with the townhome roofs. Roofs were reportedly replaced in 2017 after a major hail storm. Typically, composition shingle roofing surfaces will last twenty years in the area. Damaged downspouts were reportedly replaced with the roofs after the hailstorm in 2017. They should not require replacement for many years as this component typically provides 30 years of relatively trouble free service. The exteriors of the townhomes and the amenity center are clad in brick and stone veneer with cement fiber siding, fasciae, corner boards, and porch soffits. Stained wood shutters are installed at some front facing widows. Garage doors located at the alley side of units are painted fiberglass overhead doors. Front facing garage doors are stained wood.

Painting of the wood exterior elements on the buildings including the amenity center has been accomplished on an eight-year cycle. We suggest

caulking windows and other joints during the painting process. Staining of the wood garage doors will need to be performed on a more

frequent basis - about every four years.

Building structure and exterior is consistent with the normal performance and aging of this system.

The remaining useful life is as expected.

No unusual conditions were noted.

Common Components & Required Reserve Expenditures

Appendix A contains an inventory of all building structure and exterior items which are common components, and a detailed schedule of projected reserve expenditures for these items.

4.3.3 Building Interior

The building interior maintained by the community includes flooring material, interior paint, lighting fixtures, doors, Exercise room, furniture, and 3 bathrooms.

Powered by HomeRun IQ Page 17 of 204

The current condition of the building interior is consistent with the normal performance and aging of this system.

The remaining useful life is as expected.

No unusual conditions were noted.

Common Components & Required Reserve Expenditures

Appendix A contains an inventory of all building interior items which are common components, and a detailed schedule of projected reserve expenditures for these items.

4.3.4 Mechanical, Electrical, and Plumbing (MEP) Systems

This section of the report does not address Owner-responsible mechanical, electrical, and plumbing systems.

Description & Observations

Underground electrical wires feed exterior electric panels to accomplish electrical distribution at the amenity center and townhomes.

The irrigation controllers (22 ea.) for the landscaped areas are located throughout the community and typically attached to building exteriors. Access into the amenity center and pool area is controlled via a key fob system. A surveillance system was recently added.

Seven tons of cooling/heating are provided by the amenity center's two split-system units. Two drinking fountains are installed on the amenity center east exterior wall, and two more are located in the gym. Pool equipment is located in a mechanical closet at the south side of the amenity center. Pool equipment consists of two pumps and one sand filter.

There did not appear to be any issues of significance regarding the electrical, HVAC, or security systems at the community at the time of the investigation. Irrigation controllers and system appeared to be in fair condition and working order. The drinking fountains are in fair condition. The pool equipment is generally in fair condition. Routine maintenance and replacement of pool equipment can be expected.

Amenity center water and sewer service is provided by the City of Carrollton. Water distribution piping is copper. Sewage collection piping

is PVC. The plumbing fixtures are vitreous china, of commercial quality, with good quality accessories.

Men's Restroom

- -Two sinks
- -One urinal
- -One toilet

Women's Restroom

- Two sinks
- -Two toilets

The underground amenity central electrical system has a 120/240 volt, single phase and 220 A panels Amperage.

The current condition of the MEP systems is consistent with the normal performance and aging of this system.

Powered by HomeRun IQ Page 18 of 204

The remaining useful life is as expected.

No unusual conditions were noted.

Common Components & Required Reserve Expenditures

Appendix A contains an inventory of all MEP systems which are common components, and a detailed schedule of projected reserve expenditures for these items.

4.3.5 Amenities

Description & Observations

The pool is surfaced with gunite pool surfacing and has cast-stone coping and tile at the waterline. Pool apron/decking is stamped, stained, cast-in place concrete.

The pool should be planned for periodic resurfacing in approximately 5 years. Decking is in fair condition. Minor cracking of the surface can be expected. Regular patching/sealing should be anticipated. The decking to coping joint will require periodic resealing (Deck-O-Seal), and should be planned for in approximately 2 years and then should be resealed on a 4 year cycle. The chaises and chairs are of fair quality.

Gym equipment consists of:

- 3 treadmills
- 2 elliptical trainers
- 2 recumbent cycles
- 1 weight machine
- 2 flat screen TVs

The current condition of the amenities is consistent with the normal performance and aging of this system.

The remaining useful life is as expected.

No unusual conditions were noted.

Common Components & Required Reserve Expenditures

Appendix A contains an inventory of all amenities which are common components, and a detailed schedule of projected reserve expenditures for these items.

4.3.6 Other Items

Description & Observations

We consider these buildings and site components to be in generally good condition when compared to others of similar age and construction type. While some components are in need of a repair and replacement program, the program can be prioritized and planned in conjunction with reserve strategies. We feel that the reserve financials included with this report outline several possible strategies for the community to adopt given the current condition of the project as a whole. As time passes, it may become necessary to reestablish financial priorities and capital expenditure schedules given any unforeseen circumstances. We recommend and encourage this activity.

An annual contingency is included in reserve fund components to address unforeseen or unexpected expenses.

Powered by HomeRun IQ Page 19 of 204

We recommend the Association conduct periodic Reserve Study Updates in accordance with CAI best practices.

Common Components & Required Reserve Expenditures

Appendix A contains an inventory of all other items which are common components, and a detailed schedule of projected reserve expenditures for these items.

4.4 LIFE & VALUATION

4.4.1 Opinions of Useful Life

Simply stated, for components which require periodic reserve expenditures for their repairs or replacement, the frequency of work equals the typical, industry accepted expected useful life (EUL) for the type of feature,

And, theoretically, the remaining useful life (RUL) of a component before the next reserve expenditure for its repair or replacement is equal to the difference between its EUL and its age:

However, the condition and rate of deterioration of the association's assets rarely conform to such simple analysis. And, often, a property's history and available documentation does not provide any record of a particular component's actual age.

In our experience, the effective age and actual RUL of an installed item vary greatly from its actual age and calculated RUL. These variances depend on the quality of its original materials and workmanship, level of service, climatic exposure, and ongoing maintenance. As part of Criterium's work on this reserve study, we have determined our opinion of the effective age, EUL and RUL of each common component based on our evaluation of its existing condition and considering those factors.

When it seems appropriate, we will spread some budgets over multiple years. However, it is beyond the scope of this reserve study to prioritize the need for work between a number of buildings or installed locations or to closely specify or breakdown phased work packages.

In summary, we have based our opinion of the remaining useful life and expected frequency and schedule of repair for each common component on some or all of the following:

- · Actual or assumed age
- Observed existing condition
- Association's or Property Manager's maintenance history and plan
- · Our experience with actual performance of such components under similar service and exposure
- Our experience managing the repairs and replacements of such components

We use the following documentation to guide our considerations:

- Fannie Mae Expected Useful Life Tables National Association of Home Builders Life Expectancy of Components
- Marshall & Swift Valuation Service Expected Life Expectancies

4.4.2 Cost Estimating

In developing our estimate of reserve expenditure for most common components, we have estimated a quantity of each item and also a unit cost for its repair or replacement. In some cases, it is more appropriate to estimate a lump sum cost for a required work package or 'lot'.

Powered by HomeRun IQ Page 20 of 204

Unless directed to take a different approach, we assume that contract labor will perform the work and apply appropriate installer's mark-ups on supplied material and equipment. When required, our estimated costs include demolition and disposal of existing materials, and protection of other portions of the property.

When appropriate for large reserve projects, we will also include soft costs for design and project management, and typical general contractor's cost for general conditions, supervision, overhead and profit.

We have based our opinion of unit and lump sum costs on some or all of the following:

- · Records of previous maintenance expenses
- Previously solicited Vendor quotations or Contractor proposals
- Provided reserve budgets developed by others
- Our project files on repairs and replacements at other properties

We use the following publications to guide our considerations:

- · On-Line R S Means Construction Cost Data
- · Marshall & Swift Valuation Service Facility Cost Index

Annual aggregated reserve expenditure budgets have been calculated for all years during the study period by inflating the annual tallies of current dollar cost estimates, and compounding for inflation at 4.00% per year.

Of course, it is impossible to accurately predict inflation fluctuation. Four percent is close to the average annual values of both consumer and construction cost increases since the US Bureau of Labor Statistics started publishing data approximately 85 years ago.



5.0 FINANCIAL ANALYSIS

Please refer to Appendix A which contains tables illustrating the findings following below.

5.1 RESERVE EXPENDITURE PROJECTION

Based on our investigations and estimates described in Section 4 of this report, we have identified likely reserve expenditures throughout the study period.

For detailed information on projected reserve expenditures, please refer to the Appendix A tables titled "Common Component Inventory & Reserve Expenditure Planning" and "Annual Reserve Expenditures 30-Year Budget Projection."

Please note that we have assumed that the cost of minor repair & replacement work valued at less than \$2000 will be covered by normal Operations & Maintenance budgets.

Our projections also include a suggested minimum annual balance threshold for your funding, which is referred to as the Threshold Level. This is equal to half the average annual expenditures over the 30-year study period.

We have not included any reserve budget allowances for repair of casualty damage by vehicle impact, severe storm action, etc. It is assumed that such expenses would be defrayed by proceeds of insurance claims.

5.2 CURRENT FUNDING

5.2.1 Board-Provided Information

At the time we were retained to provide this study, The Shops at Prestonwood Home Owners Association provided us with initial information on Association's Reserve Fund and its funding plan.

Our initial financial analysis was based on the information supplied.

Fiscal Year Starting Date: Jul 1, 2024

For Designated Year: 2024

Starting Fund Balance: \$1,380,770

On Date: Jul 1, 2024

Current Rate of Contribution: \$120,000

Planned Increases: 4.18%

Planned Special Assessments: \$0

Projected Average Return on Investment: 1.50%

Projected Rate of Annual Inflation: 4.00%

Financial data, records of past expenses, and cost estimates provided by others have been taken in good faith and at face value. No audit or other verification has been performed.

5.2.2 Current Funding Plan Projection

Powered by HomeRun IQ Page 22 of 204

Our initial analysis was a projection of the Association's current rate of contribution forward over 30 years with no increases. For detailed data, please refer to the Appendix A tables and graphs titled "Reserve Fund - 30-Year Cash flow Projection - Current Funding Plan"

Given the reported \$1,380,770 starting balance of the Reserve Fund on Jul 1, 2024, the current ongoing rate of contribution of \$120,000, and an anticipated average rate of return on investment of 1.50% per year, our financial analysis indicates that the Association's current funding will prove insufficient to meet future needs.

Because of draw-downs for projected reserve expenditure expenses, projected year-end fund balances will fall into deficit in 2036 of the study period. The projected year-end balance at the end of the 30-year planning period in 2053 will be approximately (\$12,422,670).

5.3 ALTERNATIVE FUNDING PLANS

We have prepared 3 alternate funding plan for the Board's consideration:

Alternative 1 - Stairstep Funding

Minimum required funding for capital reserves over the duration without a special assessment. This
alternative recommends an increase in initial funding to \$400,000 (\$1,050 per unit annually together with
periodic increases of \$200,000 (\$525 per unit annually) every 3 years for the next 6 years, then an
increase of \$150,000 (\$394) per unit in 2033. Total monthly rates of contributions grow to \$950,000 in
Year 10, \$950,000 in Year 20 and \$950,000 in Year 30. This alternative creates an adequate fund balance
throughout the study period.

Alternative 2 - Annual Percentage Increase in Funding

• Minimum required contribution together with annual escalation in dues for capital reserves over the duration without a special assessment. This alternative recommends an increase in initial funding to \$350,000 (\$919 per unit annually), and recommends recurring annual increases in the rate of contribution equal to 10.00% in contribution over the next 12 years. Total monthly rates of contributions grow to \$825,282 in Year 10, \$1,208,295 in Year 20 and \$1,208,295 in Year 30. This alternative creates an adequate fund balance throughout the study period and also represents a solid approach.

Alternative 3 - Current Funding With Inflationary Increase and Special Assessments

 Maintains initial funding at the current level with 4.0% annual inflationary increases to contribution over the duration of the funding period. This alternative requires a large special assessment at years 11, 14, 17, and 25, but holds annual dues for the capital reserve to a minimum. This alternative is NOT recommended but shows what the financial impact will be without long-term planning.

5.4. FUNDING METHODOLOGIES (Background Information)

The Community Association Institute (CAI) recognizes several reserve funding methodologies, all of which may be used to satisfy these principles:

- Sufficient Funds When Required
- · Stable Contribution Rate over the Years
- · Evenly Distributed Contributions over the Years
- · Fiscally Responsible

For the planning needs of your association, we have recommended a cash-flow projection approach. The projection considers anticipated annual expenditures and contributions to compute approximate year-end reserve fund balances throughout the study period. This methodology is consistent with standards suggested by CAI.

Powered by HomeRun IQ Page 23 of 204

There are other methods of determining appropriate reserve funding levels. If you are interested, these are set forth in CAI's National Reserve Study Standard attached in Appendix C.



Powered by HomeRun IQ Page 24 of 204

6.0 LIMITATIONS

STANDARDS AND LIMITATIONS

Criterium-Dotson Engineers shall perform duties to at least the professional standards consistent with a licensed, Professional Engineer, but does not guarantee or warrant that all adverse conditions concerning the property can be or will be discovered and included in the report. The photographs are an integral part of this report and must be included in any review.

This study is limited to the visual observations made during our inspection. We did not undertake any excavation, conduct any destructive or invasive testing, remove surface materials or finishes, or displace furnishings or equipment. The observations described in this study are valid on the dates of the investigation.

Accordingly, we cannot comment on the condition of systems that we could not see, such as buried structures and utilities, nor are we responsible for conditions that could not be seen or were not within the scope of our services at the time of inspection.

We did not perform any computations or other engineering analysis as part of this study, nor did we conduct a comprehensive code compliance investigation.

This information in this study is not to be considered a warranty of condition, quality, compliance or cost. No warranty is implied.

Financial data, records of past expenses, and cost estimates provided by others have been taken in good faith and at face value. No audit or other verification has been performed.

Reserve budgets are opinions of likely expense based on reasonable cost estimates. We have not obtained competitive quotations or estimates from contractors. Actual costs can vary significantly, based on the specific scope of work developed, availability of materials and qualified contractors, and many other variables. We cannot be responsible for variances.

Criterium-Dotson Engineers does not offer financial counseling services. Although reasonable rates of inflation and return on investment must be assumed to calculate projected balances, no one can accurately predict actual economic performance. Although reserve fund management and investment may be discussed during the course of the study, we do not purport to hold any special qualifications in this area.

We recommend that the Board also seek other professional guidance before finalizing their current reserve fund planning activity. Depending on issues which may arise, an appropriate team of consultants to aid decision-making might include their property manager, accountant, financial counselor and attorney.

Criterium-Dotson Engineers prepared this confidential report for the review and use of the Board of the Association. We do not intend any other individual or party to rely upon this study without our express written consent. If another individual or party relies on this study, they shall indemnify, defend and hold Criterium-Dotson Engineers, its subsidiaries, affiliates, officers, directors, members, shareholders, partners, agents, employees and such other parties in interest specified by Criterium-Dotson Engineers harmless for any damages, losses, or expenses they may incur as a result of its use. Any use or reliance of the report by an individual or party other than shall constitute acceptance of these terms and conditions.

Powered by HomeRun IQ Page 25 of 204

7.0 CONCLUSION

Criterium-Dotson Engineers appreciates this opportunity to assist Legacy Southwest Property Management in support of The Shops at Prestonwood facility and financial planning. We are pleased to present this report for the Board's consideration and use.

To the best of our ability, we have attempted to work in the best interest of The Shops at Prestonwood and to aid the Board toward fulfillment of their fiduciary responsibilities and obligations to the individual Unit Owners who comprise the association's membership.

In our professional opinion, and within the limitations disclosed elsewhere herein, all information contained herein is reliable and appropriate to guide the Board's deliberations and decision-making.

All of Criterium's work for this study has been carried out in strict accordance with the CAI Code of Ethics. We consider our report confidential and will not share its content with anyone but the Board without its knowledge and release.

We are unaware of any other involvement or business relationship between Criterium-Dotson Engineers and the Developer, or individual Unit Owners, or members of the Board, or any other entities which constitute any conflict of interest.

If you have any further questions or would like to direct additional, follow-on services, please contact Criterium Dotson Engineers at 972-562-1011.

Criterium-Dotson Engineers appreciates this opportunity to assist the Board in support of the association's facility and financial planning. Thank you.

Thank you.

Respectfully submitted,

Criterium-Dotson Engineers

Summer Magdadi

David H. Dotson

Summer Magdadi David H. Dotson, PE, RS, BIE Project Engineer - (Investigating & Reporting) Reviewing Engineer - (Reviewing)

Powered by HomeRun IQ Page 26 of 204



Powered by HomeRun IQ Page 27 of 204

APPENDIX A FINANCIAL EXHIBITS

Powered by HomeRun IQ Page 28 of 204

Reserve Study for Client: Board of Directors

Property Manager: Michelle Dando

Association Information, Agreed Planning Assumptions and Current Reserve Funding Data


Association Information: Number of units Is this property mixed-use? Are all Units assessed at equal rates? Fiscal year starts Fiscal year is designated as	1 total buildings Residential property	381 Yes or No Yes or No July 1, 2024 2024
Construction History: Initial building construction or first Unit occupancy If building(s) had a prior use, the year of condo conversion If phased construction, the year the last Unit was completed Significant renovation	Not Applicable Not Applicable Not Applicable	2008
Study Information & Planning Assumptions: Study period, duration in years Study period starts Rate of return on investment % (ROI) applied to reserve fund balances Annual inflation rate (%) applied to future expenditure annual budgets		30 July 1, 2024 1.50% 4.00%
Current Funding Levels: Estimated starting reserve fund balance Current monthly reserve contribution Current overall annual reserve contribution Monthly average reserve contribution per unit Annual average reserve contribution per unit		\$1,380,770 \$8,700 \$104,400 \$23 \$274
Current Planned Special Assessments:		Dollars Year

30-Year Cash-Flow Projections - Summary Graph

Powered by HomeRun IQ

			Year-End Reserve Fund Balances					
Year No.	Fiscal Year	Projected Capital Expenditures	Current Funding Levels	Alternative 1, Level Funding with Steps	Alternative 2, Escalating Funding	Alternative 3, Escalating Funding with Special Assessments		
1	2024	\$757,624	\$763,858	\$1,043,858	\$993,858	\$763,858		
2	2025	\$163,316	\$736,800	\$1,296,200	\$1,230,450	\$736,800		
3	2026	\$117,523	\$760,122	\$1,598,121	\$1,554,885	\$760,122		
4	2027	\$153,564	\$752,944	\$2,068,529	\$1,890,494	\$752,944		
5	2028	\$56,224	\$848,397	\$2,643,333	\$2,375,063	\$848,397		
6	2029	\$84,889	\$922,233	\$3,198,094	\$2,889,479	\$922,233		
7	2030	\$90,376	\$997,529	\$3,955,690	\$3,462,492	\$997,529		
8	2031	\$177,278	\$993,125	\$4,637,747	\$4,019,202	\$993,125		
9	2032	\$1,043,543	\$128,708	\$4,463,771	\$3,786,203	\$128,708		
10	2033	\$144,924	\$156,512	\$5,335,804	\$4,523,354	\$156,512		
11	2034	\$2,784,318	(\$2,447,829)	\$3,581,523	\$2,714,696	\$552,171		
12	2035	\$145,298	(\$2,408,392)	\$4,439,948	\$3,608,710	\$599,890		
13	2036	\$255,699	(\$2,471,968)	\$5,200,848	\$4,505,591	\$545,313		
14	2037	\$3,331,341	(\$5,603,500)	\$2,897,519	\$2,450,128	\$421,961		
15	2038	\$238,247	(\$5,633,946)	\$3,652,735	\$3,456,929	\$397,844		
16	2039	\$204,943	(\$5,622,775)	\$4,452,584	\$4,512,135	\$414,983		
17	2040	\$5,223,741	(\$10,621,758)	\$245,631	\$564,371	\$422,224		
18	2041	\$150,467	(\$10,538,478)	\$1,048,848	\$1,630,664	\$511,838		
19	2042	\$258,890	(\$10,554,270)	\$1,755,691	\$2,604,529	\$503,724		
20	2043	\$65,734	(\$10,367,181)	\$2,666,293	\$3,786,158	\$698,368		
21	2044	\$97,684	(\$10,201,930)	\$3,558,604	\$4,953,562	\$874,094		
22	2045	\$426,236	(\$10,354,715)	\$4,135,746	\$5,809,924	\$734,422		
23	2046	\$250,602	(\$10,320,926)	\$4,897,181	\$6,854,766	\$779,226		
24	2047	\$305,717	(\$10,330,877)	\$5,614,922	\$7,860,165	\$780,964		
25	2048	\$2,445,714	(\$12,468,994)	\$4,203,432	\$6,740,649	\$654,561		
26	2049	\$226,311	(\$12,375,404)	\$4,990,173	\$7,823,743	\$757,969		
27	2050	\$185,337	(\$12,228,045)	\$5,829,688	\$8,964,057	\$916,698		
28	2051	\$178,831	(\$12,060,872)	\$6,688,302	\$10,127,982	\$1,097,622		
29	2052	\$835,098	(\$12,536,126)	\$6,903,529	\$10,653,098	\$638,832		
30	2053	\$260,782	(\$12,422,670)	\$7,696,299	\$11,760,407	\$761,871		

Page 30 of 204



The chart above compares the projected annual reserve fund ending balances for the three funding plans (Current Funding Levels Assessment Funding, Alternative Alternative 1, Level Funding with Steps and Alternative 2, Escalating Funding) over the 30 year period.

Future opportunity to reduce rate of contribution to reserves after key projects are complete. Consider during Reserve Study Update.

Powered by HomeRun IQ Page 31 of 204

Cash-Flow Projection at the Current Funding Levels Funding Level

Inflation: 4.00% | Investment: 1.50% | Calc: Inflation-Adjusted

YEAR	STARTING BALANCE	CONTRIBUTIONS	PERCENT CHANGE	INTEREST	SPECIAL ASSMNT	ADDTIONAL CAPITAL	EXPENDITURE FUTURE COST	ENDING BALANCE
2024-25	\$1,380,770	\$120,000	14.94%	\$20,712	\$0	\$0	\$757,624	\$763,858
2025-26	\$763,858	\$124,800	4.00%	\$11,458	\$0	\$0	\$163,316	\$736,800
2026-27	\$736,800	\$129,792	4.00%	\$11,052	\$0	\$0	\$117,523	\$760,122
2027-28	\$760,122	\$134,984	4.00%	\$11,402	\$0	\$0	\$153,564	\$752,944
2028-29	\$752,944	\$140,383	4.00%	\$11,294	\$0	\$0	\$56,224	\$848,397
2029-30	\$848,397	\$145,998	4.00%	\$12,726	\$0	\$0	\$84,889	\$922,233
2030-31	\$922,233	\$151,838	4.00%	\$13,833	\$0	\$0	\$90,376	\$997,529
2031-32	\$997,529	\$157,912	4.00%	\$14,963	\$0	\$0	\$177,278	\$993,125
2032-33	\$993,125	\$164,228	4.00%	\$14,897	\$0	\$0	\$1,043,543	\$128,708
2033-34	\$128,708	\$170,797	4.00%	\$1,931	\$0	\$0	\$144,924	\$156,512
2034-35	\$156,512	\$177,629	4.00%	\$2,348	\$0	\$0	\$2,784,318	(\$2,447,829)
2035-36	(\$2,447,829)	\$184,734	4.00%	\$0	\$0	\$0	\$145,298	(\$2,408,392)
2036-37	(\$2,408,392)	\$192,124	4.00%	\$0	\$0	\$0	\$255,699	(\$2,471,968)
2037-38	(\$2,471,968)	\$199,809	4.00%	\$0	\$0	\$0	\$3,331,341	(\$5,603,500)
2038-39	(\$5,603,500)	\$207,801	4.00%	\$0	\$0	\$0	\$238,247	(\$5,633,946)
2039-40	(\$5,633,946)	\$216,113	4.00%	\$0	\$0	\$0	\$204,943	(\$5,622,775)
2040-41	(\$5,622,775)	\$224,758	4.00%	\$0	\$0	\$0	\$5,223,741	(\$10,621,758)

Powered by HomeRun IQ
Page 32 of 204

YEAR	STARTING BALANCE	CONTRIBUTIONS	PERCENT CHANGE	INTEREST	SPECIAL ASSMNT	ADDTIONAL CAPITAL	EXPENDITURE FUTURE COST	ENDING BALANCE
2041-42	(\$10,621,758)	\$233,748	4.00%	\$0	\$0	\$0	\$150,467	(\$10,538,478)
2042-43	(\$10,538,478)	\$243,098	4.00%	\$0	\$0	\$0	\$258,890	(\$10,554,270)
2043-44	(\$10,554,270)	\$252,822	4.00%	\$0	\$0	\$0	\$65,734	(\$10,367,181)
2044-45	(\$10,367,181)	\$262,935	4.00%	\$0	\$0	\$0	\$97,684	(\$10,201,930)
2045-46	(\$10,201,930)	\$273,452	4.00%	\$0	\$0	\$0	\$426,236	(\$10,354,715)
2046-47	(\$10,354,715)	\$284,390	4.00%	\$0	\$0	\$0	\$250,602	(\$10,320,926)
2047-48	(\$10,320,926)	\$295,766	4.00%	\$0	\$0	\$0	\$305,717	(\$10,330,877)
2048-49	(\$10,330,877)	\$307,596	4.00%	\$0	\$0	\$0	\$2,445,714	(\$12,468,994)
2049-50	(\$12,468,994)	\$319,900	4.00%	\$0	\$0	\$0	\$226,311	(\$12,375,404)
2050-51	(\$12,375,404)	\$332,696	4.00%	\$0	\$0	\$0	\$185,337	(\$12,228,045)
2051-52	(\$12,228,045)	\$346,004	4.00%	\$0	\$0	\$0	\$178,831	(\$12,060,872)
2052-53	(\$12,060,872)	\$359,844	4.00%	\$0	\$0	\$0	\$835,098	(\$12,536,126)
2053-54	(\$12,536,126)	\$374,238	4.00%	\$0	\$0	\$0	\$260,782	(\$12,422,670)

Powered by HomeRun IQ
Page 33 of 204

Alternative Funding Alternative 1, Level Funding with Steps

• Minimum required funding for capital reserves over the duration without a special assessment. This alternative recommends an increase in initial funding to \$400,000 (\$1,050 per unit annually together with periodic increases of \$200,000 (\$525 per unit annually) every 3 years for the next 6 years, then an increase of \$150,000 (\$394) per unit in 2033. Total monthly rates of contributions grow to \$950,000 in Year 10, \$950,000 in Year 20 and \$950,000 in Year 30. This alternative creates an adequate fund balance throughout the study period.

Inflation: 4.00% | Investment: 1.50% | Calc: Inflation-Adjusted

YEAR	STARTING BALANCE	CONTRIBUTIONS	PERCENT CHANGE	INTEREST	SPECIAL ASSMNT	ADDTIONAL CAPITAL	EXPENDITURE FUTURE COST	ENDING BALANCE
2024-25	\$1,380,770	\$400,000	283.14%	\$20,712	\$0	\$0	\$757,624	\$1,043,858
2025-26	\$1,043,858	\$400,000	0.00%	\$15,658	\$0	\$0	\$163,316	\$1,296,200
2026-27	\$1,296,200	\$400,000	0.00%	\$19,443	\$0	\$0	\$117,523	\$1,598,121
2027-28	\$1,598,121	\$600,000	50.00%	\$23,972	\$0	\$0	\$153,564	\$2,068,529
2028-29	\$2,068,529	\$600,000	0.00%	\$31,028	\$0	\$0	\$56,224	\$2,643,333
2029-30	\$2,643,333	\$600,000	0.00%	\$39,650	\$0	\$0	\$84,889	\$3,198,094
2030-31	\$3,198,094	\$800,000	33.33%	\$47,971	\$0	\$0	\$90,376	\$3,955,690
2031-32	\$3,955,690	\$800,000	0.00%	\$59,335	\$0	\$0	\$177,278	\$4,637,747
2032-33	\$4,637,747	\$800,000	0.00%	\$69,566	\$0	\$0	\$1,043,543	\$4,463,771
2033-34	\$4,463,771	\$950,000	18.75%	\$66,957	\$0	\$0	\$144,924	\$5,335,804
2034-35	\$5,335,804	\$950,000	0.00%	\$80,037	\$0	\$0	\$2,784,318	\$3,581,523
2035-36	\$3,581,523	\$950,000	0.00%	\$53,723	\$0	\$0	\$145,298	\$4,439,948
2036-37	\$4,439,948	\$950,000	0.00%	\$66,599	\$0	\$0	\$255,699	\$5,200,848
2037-38	\$5,200,848	\$950,000	0.00%	\$78,013	\$0	\$0	\$3,331,341	\$2,897,519

Powered by HomeRun IQ
Page 34 of 204

YEAR	STARTING BALANCE	CONTRIBUTIONS	PERCENT CHANGE	INTEREST	SPECIAL ASSMNT	ADDTIONAL CAPITAL	EXPENDITURE FUTURE COST	ENDING BALANCE
2038-39	\$2,897,519	\$950,000	0.00%	\$43,463	\$0	\$0	\$238,247	\$3,652,735
2039-40	\$3,652,735	\$950,000	0.00%	\$54,791	\$0	\$0	\$204,943	\$4,452,584
2040-41	\$4,452,584	\$950,000	0.00%	\$66,789	\$0	\$0	\$5,223,741	\$245,631
2041-42	\$245,631	\$950,000	0.00%	\$3,684	\$0	\$0	\$150,467	\$1,048,848
2042-43	\$1,048,848	\$950,000	0.00%	\$15,733	\$0	\$0	\$258,890	\$1,755,691
2043-44	\$1,755,691	\$950,000	0.00%	\$26,335	\$0	\$0	\$65,734	\$2,666,293
2044-45	\$2,666,293	\$950,000	0.00%	\$39,994	\$0	\$0	\$97,684	\$3,558,604
2045-46	\$3,558,604	\$950,000	0.00%	\$53,379	\$0	\$0	\$426,236	\$4,135,746
2046-47	\$4,135,746	\$950,000	0.00%	\$62,036	\$0	\$0	\$250,602	\$4,897,181
2047-48	\$4,897,181	\$950,000	0.00%	\$73,458	\$0	\$0	\$305,717	\$5,614,922
2048-49	\$5,614,922	\$950,000	0.00%	\$84,224	\$0	\$0	\$2,445,714	\$4,203,432
2049-50	\$4,203,432	\$950,000	0.00%	\$63,051	\$0	\$0	\$226,311	\$4,990,173
2050-51	\$4,990,173	\$950,000	0.00%	\$74,853	\$0	\$0	\$185,337	\$5,829,688
2051-52	\$5,829,688	\$950,000	0.00%	\$87,445	\$0	\$0	\$178,831	\$6,688,302
2052-53	\$6,688,302	\$950,000	0.00%	\$100,325	\$0	\$0	\$835,098	\$6,903,529
2053-54	\$6,903,529	\$950,000	0.00%	\$103,553	\$0	\$0	\$260,782	\$7,696,299

Powered by HomeRun IQ
Page 35 of 204

Alternative Funding Alternative 2, Escalating Funding

• Minimum required contribution together with annual escalation in dues for capital reserves over the duration without a special assessment. This alternative recommends an increase in initial funding to \$350,000 (\$919 per unit annually), and recommends recurring annual increases in the rate of contribution equal to 10.00% in contribution over the next 12 years. Total monthly rates of contributions grow to \$825,282 in Year 10, \$1,208,295 in Year 20 and \$1,208,295 in Year 30. This alternative creates an adequate fund balance throughout the study period and also represents a solid approach.

Inflation: 4.00% | Investment: 1.50% | Calc: Inflation-Adjusted

YEAR	STARTING BALANCE	CONTRIBUTIONS	PERCENT CHANGE	INTEREST	SPECIAL ASSMNT	ADDTIONAL CAPITAL	EXPENDITURE FUTURE COST	ENDING BALANCE
2024-25	\$1,380,770	\$350,000	235.25%	\$20,712	\$0	\$0	\$757,624	\$993,858
2025-26	\$993,858	\$385,000	10.00%	\$14,908	\$0	\$0	\$163,316	\$1,230,450
2026-27	\$1,230,450	\$423,500	10.00%	\$18,457	\$0	\$0	\$117,523	\$1,554,885
2027-28	\$1,554,885	\$465,850	10.00%	\$23,323	\$0	\$0	\$153,564	\$1,890,494
2028-29	\$1,890,494	\$512,435	10.00%	\$28,357	\$0	\$0	\$56,224	\$2,375,063
2029-30	\$2,375,063	\$563,678	10.00%	\$35,626	\$0	\$0	\$84,889	\$2,889,479
2030-31	\$2,889,479	\$620,046	10.00%	\$43,342	\$0	\$0	\$90,376	\$3,462,492
2031-32	\$3,462,492	\$682,051	10.00%	\$51,937	\$0	\$0	\$177,278	\$4,019,202
2032-33	\$4,019,202	\$750,256	10.00%	\$60,288	\$0	\$0	\$1,043,543	\$3,786,203
2033-34	\$3,786,203	\$825,282	10.00%	\$56,793	\$0	\$0	\$144,924	\$4,523,354
2034-35	\$4,523,354	\$907,810	10.00%	\$67,850	\$0	\$0	\$2,784,318	\$2,714,696
2035-36	\$2,714,696	\$998,591	10.00%	\$40,720	\$0	\$0	\$145,298	\$3,608,710
2036-37	\$3,608,710	\$1,098,450	10.00%	\$54,131	\$0	\$0	\$255,699	\$4,505,591
2037-38	\$4,505,591	\$1,208,295	10.00%	\$67,584	\$0	\$0	\$3,331,341	\$2,450,128

Powered by HomeRun IQ Page 36 of 204

YEAR	STARTING BALANCE	CONTRIBUTIONS	PERCENT CHANGE	INTEREST	SPECIAL ASSMNT	ADDTIONAL CAPITAL	EXPENDITURE FUTURE COST	ENDING BALANCE
2038-39	\$2,450,128	\$1,208,295	0.00%	\$36,752	\$0	\$0	\$238,247	\$3,456,929
2039-40	\$3,456,929	\$1,208,295	0.00%	\$51,854	\$0	\$0	\$204,943	\$4,512,135
2040-41	\$4,512,135	\$1,208,295	0.00%	\$67,682	\$0	\$0	\$5,223,741	\$564,371
2041-42	\$564,371	\$1,208,295	0.00%	\$8,466	\$0	\$0	\$150,467	\$1,630,664
2042-43	\$1,630,664	\$1,208,295	0.00%	\$24,460	\$0	\$0	\$258,890	\$2,604,529
2043-44	\$2,604,529	\$1,208,295	0.00%	\$39,068	\$0	\$0	\$65,734	\$3,786,158
2044-45	\$3,786,158	\$1,208,295	0.00%	\$56,792	\$0	\$0	\$97,684	\$4,953,562
2045-46	\$4,953,562	\$1,208,295	0.00%	\$74,303	\$0	\$0	\$426,236	\$5,809,924
2046-47	\$5,809,924	\$1,208,295	0.00%	\$87,149	\$0	\$0	\$250,602	\$6,854,766
2047-48	\$6,854,766	\$1,208,295	0.00%	\$102,821	\$0	\$0	\$305,717	\$7,860,165
2048-49	\$7,860,165	\$1,208,295	0.00%	\$117,902	\$0	\$0	\$2,445,714	\$6,740,649
2049-50	\$6,740,649	\$1,208,295	0.00%	\$101,110	\$0	\$0	\$226,311	\$7,823,743
2050-51	\$7,823,743	\$1,208,295	0.00%	\$117,356	\$0	\$0	\$185,337	\$8,964,057
2051-52	\$8,964,057	\$1,208,295	0.00%	\$134,461	\$0	\$0	\$178,831	\$10,127,982
2052-53	\$10,127,982	\$1,208,295	0.00%	\$151,920	\$0	\$0	\$835,098	\$10,653,098
2053-54	\$10,653,098	\$1,208,295	0.00%	\$159,796	\$0	\$0	\$260,782	\$11,760,407

Powered by HomeRun IQ
Page 37 of 204

Alternative Funding Alternative 3, Escalating Funding with Special Assessments

• Maintains initial funding at the current level with 4.0% annual inflationary increases to contribution over the duration of the funding period. This alternative requires a large special assessment at years 11, 14, 17, and 25, but holds annual dues for the capital reserve to a minimum. This alternative is NOT recommended but shows what the financial impact will be without long-term planning.

Inflation: 4.00% | Investment: 1.50% | Calc: Inflation-Adjusted

\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0	\$757,624 \$163,316 \$117,523 \$153,564	\$763,858 \$736,800 \$760,122 \$752,944
\$0 \$0	\$0 \$0	\$117,523	\$760,122
\$0	\$0		
		\$153,564	\$752,944
\$0	\$n		
	Q0	\$56,224	\$848,397
\$0	\$0	\$84,889	\$922,233
\$0	\$0	\$90,376	\$997,529
\$0	\$0	\$177,278	\$993,125
\$0	\$0	\$1,043,543	\$128,708
\$0	\$0	\$144,924	\$156,512
\$3,000,000	\$0	\$2,784,318	\$552,171
\$0	\$0	\$145,298	\$599,890
\$0	\$0	\$255,699	\$545,313
\$3,000,000	\$0	\$3,331,341	\$421,961
\$0	\$0	\$238,247	\$397,844
	\$0 \$0 \$0 \$0 \$0 \$3,000,000 \$0 \$3,000,000	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$3,000,000 \$0 \$0 \$0 \$3,000,000 \$0	\$0 \$0 \$84,889 \$0 \$0 \$90,376 \$0 \$0 \$177,278 \$0 \$0 \$1,043,543 \$0 \$0 \$1,043,543 \$0 \$0 \$144,924 \$3,000,000 \$0 \$2,784,318 \$0 \$0 \$145,298 \$0 \$0 \$255,699 \$3,000,000 \$0 \$3,331,341

Powered by HomeRun IQ
Page 38 of 204

YEAR	STARTING BALANCE	CONTRIBUTIONS	PERCENT CHANGE	INTEREST	SPECIAL ASSMNT	ADDTIONAL CAPITAL	EXPENDITURE FUTURE COST	ENDING BALANCE
2039-40	\$397,844	\$216,113	4.00%	\$5,968	\$0	\$0	\$204,943	\$414,983
2040-41	\$414,983	\$224,758	4.00%	\$6,225	\$5,000,000	\$0	\$5,223,741	\$422,224
2041-42	\$422,224	\$233,748	4.00%	\$6,333	\$0	\$0	\$150,467	\$511,838
2042-43	\$511,838	\$243,098	4.00%	\$7,678	\$0	\$0	\$258,890	\$503,724
2043-44	\$503,724	\$252,822	4.00%	\$7,556	\$0	\$0	\$65,734	\$698,368
2044-45	\$698,368	\$262,935	4.00%	\$10,476	\$0	\$0	\$97,684	\$874,094
2045-46	\$874,094	\$273,452	4.00%	\$13,111	\$0	\$0	\$426,236	\$734,422
2046-47	\$734,422	\$284,390	4.00%	\$11,016	\$0	\$0	\$250,602	\$779,226
2047-48	\$779,226	\$295,766	4.00%	\$11,688	\$0	\$0	\$305,717	\$780,964
2048-49	\$780,964	\$307,596	4.00%	\$11,714	\$2,000,000	\$0	\$2,445,714	\$654,561
2049-50	\$654,561	\$319,900	4.00%	\$9,818	\$0	\$0	\$226,311	\$757,969
2050-51	\$757,969	\$332,696	4.00%	\$11,370	\$0	\$0	\$185,337	\$916,698
2051-52	\$916,698	\$346,004	4.00%	\$13,750	\$0	\$0	\$178,831	\$1,097,622
2052-53	\$1,097,622	\$359,844	4.00%	\$16,464	\$0	\$0	\$835,098	\$638,832
2053-54	\$638,832	\$374,238	4.00%	\$9,582	\$0	\$0	\$260,782	\$761,871

Powered by HomeRun IQ
Page 39 of 204

Current Reserve Items and Expenditure Planning

Grouped by Category

CATEGORY

COMPONENT	NEXT REPL	EXPECTED USEFUL LIFE	REMAINING USEFUL LIFE	COST PER MEASURE	QUANTITY	CURRENT COST
Amenities						
Amenity Center Furniture Replacement	01/01/2030	20:00	5:06	\$10,560.00	1 Lot	\$10,560
BBQ Grill Replacement	01/01/2025	15:00	0:06	\$1,585.00	2 Ea	\$3,170
Decking Repairs - Creekway (Periodic)	01/01/2026	10:00	1:06	\$24.00	355 SF	\$8,520
Decking Repairs - Riverview (Periodic)	01/01/2030	10:00	5:06	\$24.00	355 SF	\$8,520
Exercise Equipment - Elliptical Replacement	01/01/2026	14:00	1:06	\$5,940.00	2 Ea	\$11,880
Exercise Equipment - Spinner Replacement	01/01/2026	14:00	1:06	\$1,610.00	2 Ea	\$3,220
Exercise Equipment - Treadmill Replacement	01/01/2026	14:00	1:06	\$7,788.00	3 Ea	\$23,364
Exercise Equipment - Weight Machine Replacement	01/01/2026	14:00	1:06	\$5,940.00	1 Ea	\$5,940
Flat Screen Television Replacement	01/01/2026	10:00	1:06	\$1,848.00	2 Ea	\$3,696
Mailbox Replacement	01/01/2038	30:00	13:06	\$1,980.00	24 Ea	\$47,520
Park Bench Replacement	01/01/2033	25:00	8:06	\$1,060.00	4 Ea	\$4,240
Pool Coping to Decking Joint, Both Pools (Deck-O-Seal)	01/01/2027	4:00	2:06	\$9.00	280 LF	\$2,520
Pool Coping/Tile Replacement - Creekway	01/01/2039	30:00	14:06	\$55.00	140 LF	\$7,700

Grand Total \$7,150,422

Powered by HomeRun IQ

CATEGORY

COMPONENT	NEXT REPL	EXPECTED USEFUL LIFE	REMAINING USEFUL LIFE	COST PER MEASURE	QUANTITY	CURRENT COST
Pool Coping/Tile Replacement - Riverview	01/01/2050	30:00	25:06	\$55.00	140 LF	\$7,700
Pool Fencing - Clean/Prime/Paint (Periodic) - Creekway	01/01/2025	8:00	0:06	\$12.25	395 LF	\$4,839
Pool Fencing - Clean/Prime/Paint (Periodic) - Riverview	01/01/2026	8:00	1:06	\$12.25	395 LF	\$4,839
Pool Fencing - Replacement	01/01/2049	40:00	24:06	\$80.00	790 LF	\$63,200
Pool Furniture Replacement	01/01/2028	7:00	3:06	\$12,000.00	1 Lot	\$12,000
Pool Re-Surface (Gunite) - Creekway	01/01/2027	10:00	2:06	\$11.00	1,050 SF	\$11,550
Pool Re-Surface (Gunite) - Riverview	01/01/2030	10:00	5:06	\$8.58	1,050 SF	\$9,009
Wood Arbor Replacement	01/01/2034	25:00	9:06	\$35.00	1,250 SF	\$43,750
Amenities Total						\$297,737
Building Exterior						
Door Replacement	01/01/2034	25:00	9:06	\$924.00	9	\$8,316
Garage Door - Paint	01/01/2025	8:00	0:06	\$462.00	255 Ea	\$117,810
Garage Door - Stain	01/01/2028	5:00	3:06	\$660.00	126 Ea	\$83,160
Townhome Privacy Brick Fence, Repair	01/01/2026	10:00	1:06	\$22.00	2,028 LF	\$44,616
Townhome - 4' Metal Fence Clean, Prime, Paint	01/01/2027	10:00	2:06	\$9.00	2,738 LF	\$24,642
Townhome - Metal - 4' Fence Replacement	01/01/2049	40:00	24:06	\$60.00	2,738 LF	\$164,280
Townhome - Paint and Repair Exteriors	07/01/2024	8:00	0:00	\$1,200.00	381	\$457,200

Grand Total \$7,150,422

Powered by HomeRun IQ
Page 41 of 204

COMPONENT	NEXT REPL	EXPECTED USEFUL LIFE	REMAINING USEFUL LIFE	COST PER MEASURE	QUANTITY	CURRENT COST
Townhome - Roof and Gutter Replacement (33%)	01/01/2035	20:00	10:06	\$13,740.00	127 Ea	\$1,744,980
Townhome - Roof and Gutter Replacement (33%)	01/01/2038	20:00	13:06	\$13,740.00	127 Ea	\$1,744,980
Townhome - Roof and Gutter Replacement (33%)	01/01/2041	20:00	16:06	\$13,740.00	127 Ea	\$1,744,980
Building Exterior Total						\$6,134,964
Building Interior						
Lighting - Can Replacement	01/01/2035	25:00	10:06	\$198.00	60	\$11,880
Flooring Replacement - Carpet	01/01/2025	15:00	0:06	\$6.50	540 SF	\$3,510
Flooring Replacement - Exercise	01/01/2029	20:00	4:06	\$9.00	705 SF	\$6,345
Interior Paint	01/01/2026	8:00	1:06	\$11,000.00	1 Lot	\$11,000
Restroom Fixture Replacement	01/01/2035	25:00	10:06	\$7,260.00	1 Lot	\$7,260
Restroom Partition Replacement	01/01/2039	30:00	14:06	\$990.00	3 Ea	\$2,970
Building Interior Total						\$42,965
Mechanical						
Access Control System Replacement	07/01/2024	15:00	0:00	\$5,000.00	1 Ea	\$5,000
Ceiling Fan Replacement	01/01/2027	16:00	2:06	\$350.00	8 Ea	\$2,800
Drinking Fountain Replacement	01/01/2025	15:00	0:06	\$1,500.00	4 Ea	\$6,000
Electrical Panel Replacement	01/01/2049	40:00	24:06	\$2,775.00	3 Ea	\$8,325
Еї естпсат Рапет керіасеттепт	01/01/2049	40:00	24:06	\$2,775.00	3 Ea	\$8,32

Grand Total \$7,150,422

Powered by HomeRun IQ
Page 42 of 204

CATEGORY

COMPONENT	NEXT REPL	EXPECTED USEFUL LIFE	REMAINING USEFUL LIFE	COST PER MEASURE	QUANTITY	CURRENT COST
HVAC Replacement	01/01/2037	15:00	12:06	\$9,600.00	2 Ea	\$19,200
Irrigation Controller Replacement	07/01/2024	12:00	0:00	\$990.00	22 Ea	\$21,780
Pond Equipment Replacement	01/01/2038	15:00	13:06	\$12,000.00	1 Lot	\$12,000
Pool Filter Replacement (Large)	01/01/2030	15:00	5:06	\$3,000.00	1 Ea	\$3,000
Pool Pump Replacement (2 HP)	01/01/2025	6:00	0:06	\$2,200.00	2 Ea	\$4,400
Surveillance Camera Replacement	01/01/2025	4:00	0:06	\$429.00	10 Ea	\$4,290
Surveillance Equipment Upgrade	01/01/2030	12:00	5:06	\$6,000.00	1 Lot	\$6,000
Mechanical Total						\$92,795
Other						
Reserve Study Updates	07/01/2028	4:00	4:00	\$5,800.00	1 Ea	\$5,800
Contingency	01/01/2025	1:00	0:06	\$30,000.00	1 Ea	\$30,000
Other Total						\$35,800
Site						
Brick Perimeter Fencing Repairs - Topped w/ Metal (Periodic)	01/01/2031	10:00	6:06	\$18.00	431 LF	\$7,758
Brick Perimeter Fencing Repairs - 6' (Periodic)	01/01/2027	10:00	2:06	\$22.00	1,024 LF	\$22,528
Brick Perimeter Fencing - Topped w/ Metal	01/01/2041	30:00	16:06	\$180.00	431 LF	\$77,580
Brick Perimeter Fencing - 6'	01/01/2041	30:00	16:06	\$220.00	1,024 LF	\$225,280

Grand Total \$7,150,422

Powered by HomeRun IQ
Page 43 of 204

CATEGORY

COMPONENT	NEXT REPL	EXPECTED USEFUL LIFE	REMAINING USEFUL LIFE	COST PER MEASURE	QUANTITY	CURRENT COST
Concrete Parking Lot - Seal Joints, Stripe	01/01/2027	5:00	2:06	\$2,500.00	1 Lot	\$2,500
Concrete Walkway and Drive Repairs (Periodic)	01/01/2025	7:00	0:06	\$18.00	4,950 SF	\$89,100
Column Repairs	01/01/2026	10:00	1:06	\$280.00	14 Ea	\$3,920
Retaining Wall Repairs (~ 4')	01/01/2031	10:00	6:06	\$24,000.00	1 Lot	\$24,000
Wood Perimeter Fencing Replacement	01/01/2033	20:00	8:06	\$44.00	992 LF	\$43,648
Wood Perimeter Fencing Stain	01/01/2027	5:00	2:06	\$8.00	992 LF	\$7,936
Wrought Iron Fencing - 6' Clean/Prime/Paint (Periodic)	01/01/2028	10:00	3:06	\$12.25	305 LF	\$3,736
Wrought Iron Atop Brick Fence- Clean/Prime/Paint (Periodic)	01/01/2028	10:00	3:06	\$5.50	431 LF	\$2,370
Wrought Iron Fencing Replacement - 6'	01/01/2049	40:00	24:06	\$75.00	305 LF	\$22,875
Wrought Iron Fencing Replacement Atop Brick Fence	01/01/2049	40:00	24:06	\$30.00	431 LF	\$12,930
Site Total						\$546,161

Grand Total \$7,150,422

Powered by HomeRun IQ
Page 44 of 204

Annual Reserve Expenditure Budget Projection

Annual Expenditure Table 2024 to 2033

CATEGORY RESERVE ITEM	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033
Amenities										
Amenity Center Furniture Replacement						\$13,362				
BBQ Grill Replacement	\$3,297									
Decking Repairs - Creekway (Periodic)		\$9,215								
Decking Repairs - Riverview (Periodic)						\$10,781				
Exercise Equipment - Elliptical Replacement		\$12,849								
Exercise Equipment - Spinner Replacement		\$3,483								
Exercise Equipment - Treadmill Replacement		\$25,270								
Exercise Equipment - Weight Machine Replacement		\$6,425								
Flat Screen Television Replacement		\$3,998								
Park Bench Replacement									\$6,035	
Pool Coping to Decking Joint, Both Pools (Deck-O-Seal)			\$2,835				\$3,316			
Pool Fencing - Clean/Prime/Paint (Periodic) - Creekway	\$5,032								\$6,887	

Page 45 of 204

Powered by HomeRun IQ

CATEGORY RESERVE ITEM	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033
Pool Fencing - Clean/Prime/Paint (Periodic) - Riverview		\$5,234								\$7,163
Pool Furniture Replacement				\$14,038						
Pool Re-Surface (Gunite) - Creekway			\$12,993							
Pool Re-Surface (Gunite) - Riverview						\$11,399				
Wood Arbor Replacement										\$64,761
Total Amenities	\$8,329	\$66,474	\$15,827	\$14,038		\$35,541	\$3,316		\$12,922	\$71,924
Building Exterior										
Door Replacement										\$12,310
Garage Door - Paint	\$122,522								\$167,680	
Garage Door - Stain				\$97,285					\$118,363	
Townhome - 4' Metal Fence Clean, Prime, Paint			\$27,720							
Townhome - Paint and Repair Exteriors	\$457,200								\$625,710	
Townhome Privacy Brick Fence, Repair		\$48,256								
Total Building Exterior	\$579,722	\$48,256	\$27,720	\$97,285					\$911,753	\$12,310
Building Interior										
Flooring Replacement - Carpet	\$3,650									
Flooring Replacement - Exercise					\$7,720					
Interior Paint		\$11,898								\$16,283
Powered by HomeRun IQ									Pag	ge 46 of 204

CATEGORY RESERVE ITEM	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033
Total Building Interior	\$3,650	\$11,898			\$7,720					\$16,283
Mechanical										
Access Control System Replacement	\$5,000									
Ceiling Fan Replacement			\$3,150							
Drinking Fountain Replacement	\$6,240									
Irrigation Controller Replacement	\$21,780									
Pool Filter Replacement (Large)						\$3,796				
Pool Pump Replacement (2 HP)	\$4,576						\$5,790			
Surveillance Camera Replacement	\$4,462				\$5,219				\$6,106	
Surveillance Equipment Upgrade						\$7,592				
Total Mechanical	\$42,058		\$3,150		\$5,219	\$11,388	\$5,790		\$6,106	
Other										
Contingency	\$31,200	\$32,448	\$33,746	\$35,096	\$36,500	\$37,960	\$39,478	\$41,057	\$42,699	\$44,407
Reserve Study Updates					\$6,785				\$7,938	
Total Other	\$31,200	\$32,448	\$33,746	\$35,096	\$43,285	\$37,960	\$39,478	\$41,057	\$50,637	\$44,407
Site										
Brick Perimeter Fencing Repairs - 6' (Periodic)			\$25,341							
Brick Perimeter Fencing Repairs - Topped w/ Metal (Periodic)							\$10,209			

Powered by HomeRun IQ
Page 47 of 204

CATEGORY RESERVE ITEM	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033
Column Repairs		\$4,240								
Concrete Parking Lot - Seal Joints, Stripe			\$2,812					\$3,421		
Concrete Walkway and Drive Repairs (Periodic)	\$92,664					A		\$121,938		
Retaining Wall Repairs (~ 4')							\$31,582			
Wood Perimeter Fencing Replacement									\$62,125	
Wood Perimeter Fencing Stain			\$8,927					\$10,861		
Wrought Iron Atop Brick Fence- Clean/ Prime/Paint (Periodic)				\$2,773						
Wrought Iron Fencing - 6' Clean/ Prime/Paint (Periodic)				\$4,371						
Total Site	\$92,664	\$4,240	\$37,080	\$7,144			\$41,791	\$136,221	\$62,125	
Total	\$757,624	\$163,316	\$117,523	\$153,564	\$56,224	\$84,889	\$90,376	\$177,278	\$1,043,543	\$144,924

Powered by HomeRun IQ

Annual Reserve Expenditure Budget Projection

Annual Expenditure Table 2034 to 2043

ATEGORY RESERVE ITEM	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043
Amenities										
BBQ Grill Replacement						\$5,937				
Decking Repairs - Creekway (Periodic)		\$13,641								
Decking Repairs - Riverview (Periodic)						\$15,958				
Exercise Equipment - Elliptical Replacement						\$22,251	Ţ			
Exercise Equipment - Spinner Replacement						\$6,031				
Exercise Equipment - Treadmill Replacement						\$43,760				
Exercise Equipment - Weight Machine Replacement						\$11,126				
Flat Screen Television Replacement		\$5,917								
Mailbox Replacement				\$82,289						
Pool Coping to Decking Joint, Both Pools (Deck-O-Seal)	\$3,879				\$4,538				\$5,309	
Pool Coping/Tile Replacement - Creekway					\$13,867					
Pool Fencing - Clean/Prime/Paint (Periodic) - Creekway							\$9,425			

Powered by HomeRun IQ
Page 49 of 204

CATEGORY RESERVE ITEM	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043
Pool Fencing - Clean/Prime/Paint (Periodic) - Riverview								\$9,802		
Pool Furniture Replacement	\$18,473							\$24,310		
Pool Re-Surface (Gunite) - Creekway			\$19,232							
Pool Re-Surface (Gunite) - Riverview						\$16,874				
Total Amenities	\$22,353	\$19,558	\$19,232	\$82,289	\$18,406	\$121,937	\$9,425	\$34,112	\$5,309	
Building Exterior										
Garage Door - Paint							\$229,482			
Garage Door - Stain				\$144,006					\$175,206	
Townhome - 4' Metal Fence Clean, Prime, Paint			\$41,032							
Townhome - Paint and Repair Exteriors							\$856,327			
Townhome - Roof and Gutter Replacement (33%)	\$2,686,317									
Townhome - Roof and Gutter Replacement (33%)				\$3,021,741						
Townhome - Roof and Gutter Replacement (33%)							\$3,399,047			
Townhome Privacy Brick Fence, Repair		\$71,432								
Total Building Exterior	\$2,686,317	\$71,432	\$41,032	\$3,165,747			\$4,484,856		\$175,206	
Building Interior										

Powered by HomeRun IQ Page 50 of 204

CATEGORY RESERVE ITEM	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043
Flooring Replacement - Carpet						\$6,574				
Interior Paint								\$22,284		
Lighting - Can Replacement	\$18,289									
Restroom Fixture Replacement	\$11,176									
Restroom Partition Replacement					\$5,349					
Total Building Interior	\$29,465				\$5,349	\$6,574		\$22,284		
Mechanical										
Access Control System Replacement						\$9,005				
Ceiling Fan Replacement									\$5,899	
Drinking Fountain Replacement						\$11,238				
HVAC Replacement			\$31,969							
Irrigation Controller Replacement			\$34,870							
Pond Equipment Replacement				\$20,780						
Pool Pump Replacement (2 HP)			\$7,326						\$9,270	
Surveillance Camera Replacement			\$7,143				\$8,356			
Surveillance Equipment Upgrade								\$12,155		
Total Mechanical			\$81,309	\$20,780		\$20,243	\$8,356	\$12,155	\$15,169	
Other										
Contingency	\$46,184	\$48,031	\$49,952	\$51,950	\$54,028	\$56,189	\$58,437	\$60,774	\$63,205	\$65,734

Powered by HomeRun IQ
Page 51 of 204

CATEGORY RESERVE ITEM	2034	2035	2036	2037	2038	2039	2040	2041	2042	204
Reserve Study Updates			\$9,286				\$10,863			
otal Other	\$46,184	\$48,031	\$59,238	\$51,950	\$54,028	\$56,189	\$69,300	\$60,774	\$63,205	\$65,73
bite										
Brick Perimeter Fencing - 6'							\$438,823			
Brick Perimeter Fencing - Topped w/ Metal							\$151,118			
Brick Perimeter Fencing Repairs - 6' (Periodic)			\$37,511							
Brick Perimeter Fencing Repairs - Topped w/ Metal (Periodic)							\$15,112			
Column Repairs		\$6,276								
Concrete Parking Lot - Seal Joints, Stripe			\$4,163					\$5,065		
Concrete Walkway and Drive Repairs (Periodic)					\$160,464					
Retaining Wall Repairs (~ 4')							\$46,750			
Wood Perimeter Fencing Stain			\$13,214					\$16,077		
Wrought Iron Atop Brick Fence- Clean/ Prime/Paint (Periodic)				\$4,105						
Wrought Iron Fencing - 6' Clean/ Prime/Paint (Periodic)				\$6,470						
otal Site		\$6,276	\$54,888	\$10,575	\$160,464		\$651,802	\$21,142		
- Total	\$2,784,318	\$145,298	\$255,699	\$3,331,341	\$238,247	\$204,943	\$5,223,741	\$150,467	\$258,890	\$65,73
owered by HomeRun IQ									Pag	ge 52 of 20

Annual Reserve Expenditure Budget Projection

Annual Expenditure Table 2044 to 2053

CATEGORY RESERVE ITEM	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053
Amenities										
Amenity Center Furniture Replacement						\$29,277				
Decking Repairs - Creekway (Periodic)		\$20,192								
Decking Repairs - Riverview (Periodic)						\$23,621				
Exercise Equipment - Elliptical Replacement										\$38,532
Exercise Equipment - Spinner Replacement										\$10,444
Exercise Equipment - Treadmill Replacement										\$75,779
Exercise Equipment - Weight Machine Replacement										\$19,266
Flat Screen Television Replacement		\$8,759								
Pool Coping to Decking Joint, Both Pools (Deck-O-Seal)			\$6,211				\$7,266			
Pool Coping/Tile Replacement - Riverview						\$21,348				
Pool Fencing - Clean/Prime/Paint (Periodic) - Creekway					\$12,899					

Powered by HomeRun IQ
Page 53 of 204

CATEGORY RESERVE ITEM	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053
Pool Fencing - Clean/Prime/Paint (Periodic) - Riverview						\$13,415				
Pool Fencing - Replacement					\$168,481					
Pool Furniture Replacement					\$31,990					
Pool Re-Surface (Gunite) - Creekway			\$28,468							
Pool Re-Surface (Gunite) - Riverview						\$24,977				
Total Amenities		\$28,951	\$34,679		\$213,370	\$112,639	\$7,266			\$144,020
Building Exterior										
Garage Door - Paint					\$314,062					
Garage Door - Stain				\$213,164					\$259,347	
Townhome - 4' Metal Fence Clean, Prime, Paint			\$60,734							
Townhome - Metal - 4' Fence Replacement					\$437,943					
Townhome - Paint and Repair Exteriors					\$1,171,943					
Townhome Privacy Brick Fence, Repair		\$105,736								
Total Building Exterior		\$105,736	\$60,734	\$213,164	\$1,923,948				\$259,347	
Building Interior										
Flooring Replacement - Exercise					\$16,915					
Interior Paint						\$30,497				

Powered by HomeRun IQ
Page 54 of 204

CATEGORY RESERVE ITEM	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053
Total Building Interior					\$16,915	\$30,497				
Mechanical										
Electrical Panel Replacement					\$22,193					
HVAC Replacement								\$57,575		
Irrigation Controller Replacement					\$55,829					
Pond Equipment Replacement									\$37,424	
Pool Filter Replacement (Large)	\$6,836									
Pool Pump Replacement (2 HP)					\$11,730					
Surveillance Camera Replacement	\$9,776				\$11,436				\$13,379	
Surveillance Equipment Upgrade										\$19,460
Total Mechanical	\$16,612				\$101,188			\$57,575	\$50,803	\$19,460
Other										
Contingency	\$68,363	\$71,098	\$73,941	\$76,899	\$79,975	\$83,174	\$86,501	\$89,961	\$93,560	\$97,302
Reserve Study Updates	\$12,709				\$14,867				\$17,392	
Total Other	\$81,072	\$71,098	\$73,941	\$76,899	\$94,842	\$83,174	\$86,501	\$89,961	\$110,952	\$97,302
Site										
Brick Perimeter Fencing Repairs - 6' (Periodic)			\$55,525							
Brick Perimeter Fencing Repairs - Topped w/ Metal (Periodic)							\$22,369			

Powered by HomeRun IQ
Page 55 of 204

CATEGORY RESERVE ITEM	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053
Column Repairs		\$9,290								
Concrete Parking Lot - Seal Joints, Stripe			\$6,162					\$7,497		
Concrete Walkway and Drive Repairs (Periodic)		\$211,162							\$277,873	
Retaining Wall Repairs (~ 4')							\$69,201			
Wood Perimeter Fencing Replacement									\$136,123	
Wood Perimeter Fencing Stain			\$19,560					\$23,798		
Wrought Iron Atop Brick Fence- Clean/ Prime/Paint (Periodic)				\$6,076						
Wrought Iron Fencing - 6' Clean/ Prime/Paint (Periodic)				\$9,577						
Wrought Iron Fencing Replacement - 6'					\$60,981					
Wrought Iron Fencing Replacement Atop Brick Fence					\$34,469					
Total Site		\$220,452	\$81,247	\$15,653	\$95,450		\$91,570	\$31,295	\$413,996	
Total	\$97,684	\$426,236	\$250,602	\$305,717	\$2,445,714	\$226,311	\$185,337	\$178,831	\$835,098	\$260,782

Powered by HomeRun IQ
Page 56 of 204

Upcoming Expenditures in Years 1 and 2

ASSET №	NAME	UNIT COST	QTY.	FUTURE COST	USEFUL LIFE	NEXT ACTIVITY
2024-25 (Yea	ar 1)					
33	Access Control System Replacement	\$5,000.00	1 Ea	\$5,000	15y	2039-40
48	BBQ Grill Replacement	\$1,648.40	2 Ea	\$3,297	15y	2039-40
06	Concrete Walkway and Drive Repairs (Periodic)	\$18.72	4,950 SF	\$92,664	7y	2031-32
72	Contingency	\$31,200.00	1 Ea	\$31,200	1y	2025-26
35	Drinking Fountain Replacement	\$1,560.00	4 Ea	\$6,240	15y	2039-40
26	Flooring Replacement - Carpet	\$6.76	540 SF	\$3,650	15y	2039-40
16	Garage Door - Paint	\$480.48	255 Ea	\$122,522	8y	2032-33
38	Irrigation Controller Replacement	\$990.00	22 Ea	\$21,780	12y	2036-37
63	Pool Fencing - Clean/Prime/Paint (Periodic) - Creekway	\$12.74	395 LF	\$5,032	8y	2032-33
42	Pool Pump Replacement (2 HP)	\$2,288.00	2 Ea	\$4,576	бу	2030-31
43	Surveillance Camera Replacement	\$446.16	10 Ea	\$4,462	4y	2028-29
22	Townhome - Paint and Repair Exteriors	\$1,200.00	381	\$457,200	8y	2032-33
2024-25 (Yea	ar 1) Total			\$757,624		

Powered by HomeRun IQ Page 57 of 204

ASSET №	NAME	UNIT COST	QTY.	FUTURE COST	USEFUL LIFE	NEXT ACTIVITY
2025-26 (Yea	т 2)					
07	Column Repairs	\$302.848	14 Ea	\$4,240	10y	2035-36
72	Contingency	\$32,448.00	1 Ea	\$32,448	1y	2026-27
49	Decking Repairs - Creekway (Periodic)	\$25.958	355 SF	\$9,215	10y	2035-36
51	Exercise Equipment - Elliptical Replacement	\$6,424.705	2 Ea	\$12,849	14y	2039-40
52	Exercise Equipment - Spinner Replacement	\$1,741.375	2 Ea	\$3,483	14y	2039-40
53	Exercise Equipment - Treadmill Replacement	\$8,423.50	3 Ea	\$25,270	14y	2039-40
54	Exercise Equipment - Weight Machine Replacement	\$6,424.70	1 Ea	\$6,425	14y	2039-40
55	Flat Screen Television Replacement	\$1,998.795	2 Ea	\$3,998	10y	2035-36
28	Interior Paint	\$11,897.60	1 Lot	\$11,898	8y	2033-34
64	Pool Fencing - Clean/Prime/Paint (Periodic) - Riverview	\$13.25	395 LF	\$5,234	8y	2033-34
19	Townhome Privacy Brick Fence, Repair	\$23.795	2,028 LF	\$48,256	10y	2035-36
2025-26 (Yea	ır 2) Total			\$163,316		

Powered by HomeRun IQ Page 58 of 204

Reserve Expenditure Budget Projection Summary

YEAR	FUTURE DOLLARS
2024	\$757,624
2025	\$163,316
2026	\$117,523
2027	\$153,564
2028	\$56,224
2029	\$84,889
2030	\$90,376
2031	\$177,278
2032	\$1,043,543
2033	\$144,924
2034	\$2,784,318
2035	\$145,298
2036	\$255,699
2037	\$3,331,341
2038	\$238,247
2039	\$204,943
2040	\$5,223,741
2041	\$150,467
2042	\$258,890
2043	\$65,734
2044	\$97,684
2045	\$426,236
2046	\$250,602
2047	\$305,717
2048	\$2,445,714
2049	\$226,311
2050	\$185,337
2051	\$178,831
2052	\$835,098
2053	\$260,782
Total Future Cost - With Inflation	s \$20,660,247
Total Current Cost - No Inflation	\$18,961,120
Average Annual Expenditures	\$688,675

Powered by HomeRun IQ Page 59 of 204



Powered by HomeRun IQ Page 60 of 204

APPENDIX B PHOTOGRAPHS

Powered by HomeRun IQ Page 61 of 204

Component Details

01 - Brick Perimeter Fencing Repairs - Topped w/ Metal (Periodic)

Basic Info

Type of Cost: Repairs & Maintenance

Category: Site

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 6y 6m

Next Activity Date: 01/01/2031

Financial Data

06/24/2024
CDE
\$18.00
431 LF
\$7,758
4.00%
\$47,690

Powered by HomeRun IQ Page 62 of 204



Brick Perimeter Fence Topped with Metal Fence

Powered by HomeRun IQ Page 63 of 204

02 - Brick Perimeter Fencing Repairs - 6' (Periodic)

Basic Info

Type of Cost: Repairs & Maintenance

Category: Site

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 2y 6m

Next Activity Date: 01/01/2027

Financial Data

 Estimate Date:
 04/16/2024

 Cost Per LF:
 \$22.00

 Total Quantity:
 1,024 LF

 Total Current Cost:
 \$22,528

 Inflation Rate:
 4.00%

 Total Expenditures:
 \$118,377



Brick Perimeter Fence

Powered by HomeRun IQ Page 64 of 204

03 - Brick Perimeter Fencing - Topped w/ Metal

Fair

Basic Info

Type of Cost: Replacement Category: Site Condition:

Comments/Notes

Topped with metal fence

Useful Life

Last Activity Date: N/A Est. Useful Life: 30y Remaining Useful Life: 16y 6m **Next Activity Date:** 01/01/2041

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$180.00
Total Quantity:	431 LF
Total Current Cost:	\$77,580
Inflation Rate:	4.00%
Total Expenditures:	\$151,118

Powered by HomeRun IQ Page 65 of 204

04 - Brick Perimeter Fencing - 6'

Basic Info

Type of Cost: Replacement

Category: Site

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 30y

Remaining Useful Life: 16y 6m

Next Activity Date: 01/01/2041

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$220.00
Total Quantity:	1,024 LF
Total Current Cost:	\$225,280
Inflation Rate:	4.00%
Total Expenditures:	\$438,823

Powered by HomeRun IQ Page 66 of 204

05 - Concrete Parking Lot - Seal Joints, Stripe

Basic Info

Type of Cost: Repairs & Maintenance

Category: Site

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 5y

Remaining Useful Life: 2y 6m

Next Activity Date: 01/01/2027

Financial Data

 Estimate Date:
 04/16/2024

 Cost Per Lot:
 \$2,500.00

 Total Quantity:
 1 Lot

 Total Current Cost:
 \$2,500

 Inflation Rate:
 4.00%

 Total Expenditures:
 \$29,119



Concrete Parking Spaces

Powered by HomeRun IQ Page 67 of 204

06 - Concrete Walkway and Drive Repairs (Periodic)

Basic Info

Type of Cost: Repairs & Maintenance

Category: Site

Condition: Fair

Comments/Notes

10% of total

Useful Life

Last Activity Date: N/A

Est. Useful Life: 7y

Remaining Useful Life: 0y 6m

Next Activity Date: 01/01/2025

Financial Data

Estimate Date: 07/01/2024

Estimate Source: CDE

Cost Per SF: \$18.00

Total Quantity: 4,950 SF

Total Current Cost: \$89,100

Inflation Rate: 4.00%

Total Expenditures: \$864,102



Concrete Walkway



Concrete sidewalk trip hazards were observed in isolated locations

Powered by HomeRun IQ Page 68 of 204

07 - Column Repairs

Basic Info

Type of Cost: Repairs & Maintenance

Category: Site

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 1y 6m

Next Activity Date: 01/01/2026

Financial Data

Estimate Date: 07/01/2024

Cost Per Ea: \$280.00

Total Quantity: 14 Ea

Total Current Cost: \$3,920

Inflation Rate: 4.00%

Total Expenditures: \$19,806



Pilaster

Powered by HomeRun IQ Page 69 of 204

08 - Retaining Wall Repairs (~ 4')

Basic Info

Type of Cost: Repairs & Maintenance

Category: Site

Condition: Unknown

Comments/Notes

\$8k done in '17

Retaining Wall

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 6y 6m

Next Activity Date: 01/01/2031

Financial Data

Estimate Date:	04/16/2024
Cost Per Lot:	\$24,000.00
Total Quantity:	1 Lot
Total Current Cost:	\$24,000
Inflation Rate:	4.00%
Total Expenditures:	\$147,533

Powered by HomeRun IQ Page 70 of 204

09 - Wood Perimeter Fencing Replacement

Basic Info

Type of Cost: Replacement

Category: Site

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 20y

Remaining Useful Life: 8y 6m

Next Activity Date: 01/01/2033

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$44.00
Total Quantity:	992 LF
Total Current Cost:	\$43,648
Inflation Rate:	4.00%
Total Expenditures:	\$198,248

Powered by HomeRun IQ Page 71 of 204

10 - Wood Perimeter Fencing Stain

Basic Info

Type of Cost: Repairs & Maintenance

Category: Site

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 5y

Remaining Useful Life: 2y 6m

Next Activity Date: 01/01/2027

Financial Data

Estimate Date: 04/16/2024

Cost Per LF: \$8.00

Total Quantity: 992 LF

Total Current Cost: \$7,936

Inflation Rate: 4.00%

Total Expenditures: \$92,439

Powered by HomeRun IQ Page 72 of 204

11 - Wrought Iron Fencing - 6' Clean/Prime/Paint (Periodic)

Basic Info

Type of Cost: Repairs & Maintenance
Category: Site
Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 3y 6m

Next Activity Date: 01/01/2028

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$12.25
Total Quantity:	305 LF
Total Current Cost:	\$3,736
Inflation Rate:	4.00%
Total Expenditures:	\$20,418

Powered by HomeRun IQ Page 73 of 204

12 - Wrought Iron Atop Brick Fence- Clean/Prime/Paint (Periodic)

Basic Info

Type of Cost: Repairs & Maintenance

Category: Site

Condition: Fair

Comments/Notes

2ft on top of brick fence

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 3y 6m

Next Activity Date: 01/01/2028

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$5.50
Total Quantity:	431 LF
Total Current Cost:	\$2,370
Inflation Rate:	4.00%
Total Expenditures:	\$12,954

Powered by HomeRun IQ Page 74 of 204

13 - Wrought Iron Fencing Replacement - 6'

Basic Info

Type of Cost: Replacement

Category: Site

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 40y

Remaining Useful Life: 24y 6m

Next Activity Date: 01/01/2049

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$75.00
Total Quantity:	305 LF
Total Current Cost:	\$22,875
Inflation Rate:	4.00%
Total Expenditures:	\$60,981

Powered by HomeRun IQ Page 75 of 204

14 - Wrought Iron Fencing Replacement Atop Brick Fence

Basic Info

Type of Cost: Replacement

Category: Site

Condition: Unknown

Comments/Notes

2ft on top of brick fence

Useful Life

Last Activity Date: N/A

Est. Useful Life: 40y

Remaining Useful Life: 24y 6m

Next Activity Date: 01/01/2049

Financial Data

Total Expenditures:

Estimate Date: 04/16/2024

Cost Per LF: \$30.00

Total Quantity: 431 LF

Total Current Cost: \$12,930

Inflation Rate: 4.00%

\$34,469

Powered by HomeRun IQ Page 76 of 204

15 - Door Replacement

Basic Info

Type of Cost: Replacement

Category: Building Exterior

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 25y

Remaining Useful Life: 9y 6m

Next Activity Date: 01/01/2034

Financial Data

Estimate Date:	04/16/2024
Cost Per :	\$924.00
Total Quantity:	9
Total Current Cost:	\$8,316
Inflation Rate:	4.00%
Total Expenditures:	\$12,310



Doors

Powered by HomeRun IQ Page 77 of 204

16 - Garage Door - Paint

Basic Info

Type of Cost: Repairs & Maintenance

Category: Building Exterior

Condition: Fair

Comments/Notes

Miracle Door pricing



Garage Doors

Useful Life

Last Activity Date: N/A

Est. Useful Life: 8y

Remaining Useful Life: 0y 6m

Next Activity Date: 01/01/2025

Financial Data

 Estimate Date:
 04/16/2024

 Cost Per Ea:
 \$462.00

 Total Quantity:
 255 Ea

 Total Current Cost:
 \$117,810

 Inflation Rate:
 4.00%

 Total Expenditures:
 \$833,747

Powered by HomeRun IQ Page 78 of 204

17 - Garage Door - Stain

Basic Info

Type of Cost: Repairs & Maintenance

Category: Building Exterior

Condition: Fair

Comments/Notes

Includes armor guard

Garage Doors and Exterior Components

Useful Life

Last Activity Date: N/A

Est. Useful Life: 5y

Remaining Useful Life: 3y 6m

Next Activity Date: 01/01/2028

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$660.00
Total Quantity:	126 Ea
Total Current Cost:	\$83,160
Inflation Rate:	4.00%
Total Expenditures:	\$1,007,371

Powered by HomeRun IQ Page 79 of 204

19 - Townhome Privacy Brick Fence, Repair

Basic Info

Type of Cost: Repairs & Maintenance

Category: Building Exterior

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 1y 6m

Next Activity Date: 01/01/2026

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$22.00
Total Quantity:	2,028 LF
Total Current Cost:	\$44,616
Inflation Rate:	4.00%
Total Expenditures:	\$225,424

Powered by HomeRun IQ Page 80 of 204

20 - Townhome - 4' Metal Fence Clean, Prime, Paint

Basic Info

Type of Cost: Repairs & Maintenance

Category: Building Exterior

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 2y 6m

Next Activity Date: 01/01/2027

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$9.00
Total Quantity:	2,738 LF
Total Current Cost:	\$24,642
Inflation Rate:	4.00%
Total Expenditures:	\$129,486

Powered by HomeRun IQ Page 81 of 204

21 - Townhome - Metal - 4' Fence Replacement

Basic Info

Type of Cost: Replacement

Category: Building Exterior

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 40y

Remaining Useful Life: 24y 6m

Next Activity Date: 01/01/2049

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$60.00
Total Quantity:	2,738 LF
Total Current Cost:	\$164,280
Inflation Rate:	4.00%
Total Expenditures:	\$437,943

Powered by HomeRun IQ Page 82 of 204

22 - Townhome - Paint and Repair Exteriors

Basic Info

Type of Cost: Repairs & Maintenance

Category: Building Exterior

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 8y

Remaining Useful Life: 0y

Next Activity Date: 07/01/2024

Financial Data

Estimate Date: 04/16/2024

Cost Per: \$1,200.00

Total Quantity: 381

Total Current Cost: \$457,200

Inflation Rate: 4.00%

Total Expenditures: \$3,111,179

Powered by HomeRun IQ Page 83 of 204

23 - Townhome - Roof and Gutter Replacement (33%)

Basic Info

Type of Cost: Replacement

Category: Building Exterior

Condition: Fair

Comments/Notes

Based on recent replacement cost

Useful Life

Last Activity Date: N/A
Est. Useful Life: 20y

Remaining Useful Life: 10y 6m

Next Activity Date: 01/01/2035

Financial Data

Estimate Date: 04/16/2024

Cost Per Ea: \$13,740.00

Total Quantity: 127 Ea

Total Current Cost: \$1,744,980

Inflation Rate: 4.00%

Total Expenditures: \$2,686,317



24 - Townhome - Roof and Gutter Replacement (33%)

Basic Info

Type of Cost: Replacement

Category: Building Exterior

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 20y

Remaining Useful Life: 13y 6m

Next Activity Date: 01/01/2038

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$13,740.00
Total Quantity:	127 Ea
Total Current Cost:	\$1,744,980
Inflation Rate:	4.00%
Total Expenditures:	\$3,021,741

Powered by HomeRun IQ Page 85 of 204

25 - Townhome - Roof and Gutter Replacement (33%)

Basic Info

Type of Cost: Replacement

Category: Building Exterior

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 20y

Remaining Useful Life: 16y 6m

Next Activity Date: 01/01/2041

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$13,740.00
Total Quantity:	127 Ea
Total Current Cost:	\$1,744,980
Inflation Rate:	4.00%
Total Expenditures:	\$3,399,047

Powered by HomeRun IQ Page 86 of 204

26 - Flooring Replacement - Carpet

Basic Info

Type of Cost: Replacement

Category: Building Interior

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 15y

Remaining Useful Life: 0y 6m

Next Activity Date: 01/01/2025

Financial Data

Estimate Date:	04/16/2024
Cost Per SF:	\$6.50
Total Quantity:	540 SF
Total Current Cost:	\$3,510
Inflation Rate:	4.00%
Total Expenditures:	\$10,224

Powered by HomeRun IQ Page 87 of 204

27 - Flooring Replacement - Exercise

Basic Info

Type of Cost: Replacement

Category: Building Interior

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 20y

Remaining Useful Life: 4y 6m

Next Activity Date: 01/01/2029

Financial Data

Estimate Date:	04/16/2024
Cost Per SF:	\$9.00
Total Quantity:	705 SF
Total Current Cost:	\$6,345
Inflation Rate:	4.00%
Total Expenditures:	\$24,635

Powered by HomeRun IQ Page 88 of 204

28 - Interior Paint

Basic Info

Type of Cost: Repairs & Maintenance

Category: Building Interior

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 8y

Remaining Useful Life: 1y 6m

Next Activity Date: 01/01/2026

Financial Data

 Estimate Date:
 04/16/2024

 Cost Per Lot:
 \$11,000.00

 Total Quantity:
 1 Lot

 Total Current Cost:
 \$11,000

 Inflation Rate:
 4.00%

 Total Expenditures:
 \$80,961

Powered by HomeRun IQ Page 89 of 204

029 - Lighting - Can Replacement

Basic Info

Type of Cost:	Replacement
Category:	Building Interior
Condition:	Fair

Paint, Furniture, Floor, and Can Lights

Useful Life

Last Activity Date:	N/A
Est. Useful Life:	25y
Remaining Useful Life:	10y 6m
Next Activity Date:	01/01/2035

Financial Data

Estimate Date:	04/16/2024
Cost Per:	\$198.00
Total Quantity:	60
Total Current Cost:	\$11,880
Inflation Rate:	4.00%
Total Expenditures:	\$18,289

Powered by HomeRun IQ Page 90 of 204

31 - Restroom Fixture Replacement

Basic Info

Type of Cost: Replacement

Category: Building Interior

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 25y

Remaining Useful Life: 10y 6m

Next Activity Date: 01/01/2035

Financial Data

Estimate Date:	04/16/2024
Cost Per Lot:	\$7,260.00
Total Quantity:	1 Lot
Total Current Cost:	\$7,260
Inflation Rate:	4.00%
Total Expenditures:	\$11,176

Powered by HomeRun IQ Page 91 of 204

32 - Restroom Partition Replacement

Basic Info

Type of Cost:	Replacement
Category:	Building Interior
Condition:	Fair

Useful Life

Last Activity Date:	N/A
Est. Useful Life:	30y
Remaining Useful Life:	14y 6m
Next Activity Date:	01/01/2039

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$990.00
Total Quantity:	3 Ea
Total Current Cost:	\$2,970
Inflation Rate:	4.00%
Total Expenditures:	\$5,349



Restroom Partition

Powered by HomeRun IQ Page 92 of 204

33 - Access Control System Replacement

Basic Info

Type of Cost:	Replacement
Category:	Mechanical
Condition:	Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 15y

Remaining Useful Life: 0y

Next Activity Date: 07/01/2024

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$5,000.00
Total Quantity:	1 Ea
Total Current Cost:	\$5,000
Inflation Rate:	4.00%
Total Expenditures:	\$14,005

Powered by HomeRun IQ Page 93 of 204

34 - Ceiling Fan Replacement

Basic Info

Type of Cost: Replacement

Category: Mechanical

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 16y

Remaining Useful Life: 2y 6m

Next Activity Date: 01/01/2027

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$350.00
Total Quantity:	8 Ea
Total Current Cost:	\$2,800
Inflation Rate:	4.00%
Total Expenditures:	\$9,049

Powered by HomeRun IQ Page 94 of 204

35 - Drinking Fountain Replacement

Basic Info

Type of Cost: Replacement

Category: Mechanical

Condition: Fair

Comments/Notes

Elkway

WHEN ILL WITH ACONTOCHUS OR ME PROHIBITED USE WHEN ILL WITH DIARRHEADR IDMITIONS PROHIBITED IS PROHIBITED IN PROHIBITED IN PROHIBITED WIST OF THE GAIL WEST OF THE GAIL

Drinking Fountain

Useful Life

Last Activity Date: N/A

Est. Useful Life: 15y

Remaining Useful Life: 0y 6m

Next Activity Date: 01/01/2025

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$1,500.00
Total Quantity:	4 Ea
Total Current Cost:	\$6,000
Inflation Rate:	4.00%
Total Expenditures:	\$17,478

Powered by HomeRun IQ Page 95 of 204

36 - Electrical Panel Replacement

Basic Info

Type of Cost: Replacement

Category: Mechanical

Condition: Fair

Comments/Notes

Amenity center, pools

Useful Life

Last Activity Date: N/A
Est. Useful Life: 40y
Remaining Useful Life: 24y 6m

Next Activity Date: 01/01/2049

Financial Data

Estimate Date: 04/16/2024

Cost Per Ea: \$2,775.00

Total Quantity: 3 Ea

Total Current Cost: \$8,325

Inflation Rate: 4.00%

Total Expenditures: \$22,193

Powered by HomeRun IQ Page 96 of 204

37 - HVAC Replacement

Basic Info

Type of Cost: Replacement

Category: Mechanical

Condition: Unknown

Comments/Notes

4 ton, 3 ton

Replaced in 2020

AIRMAX WW.Airrama.os

HVAC

Useful Life

Last Activity Date: N/A

Est. Useful Life: 15y

Remaining Useful Life: 12y 6m

Next Activity Date: 01/01/2037

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$9,600.00
Total Quantity:	2 Ea
Total Current Cost:	\$19,200
Inflation Rate:	4.00%
Total Expenditures:	\$89,545

Powered by HomeRun IQ Page 97 of 204

38 - Irrigation Controller Replacement

Basic Info

Type of Cost: Replacement

Category: Mechanical

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 12y

Remaining Useful Life: 0y

Next Activity Date: 07/01/2024

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$990.00
Total Quantity:	22 Ea
Total Current Cost:	\$21,780
Inflation Rate:	4.00%
Total Expenditures:	\$112,479

Powered by HomeRun IQ Page 98 of 204

39 - Pond Equipment Replacement

Basic Info

Type of Cost: Replacement

Category: Mechanical

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 15y

Remaining Useful Life: 13y 6m

Next Activity Date: 01/01/2038

Financial Data

Estimate Date:	04/16/2024
Cost Per Lot:	\$12,000.00
Total Quantity:	1 Lot
Total Current Cost:	\$12,000
Inflation Rate:	4.00%
Total Expenditures:	\$58,204



Pond Equipment

Powered by HomeRun IQ Page 99 of 204

41 - Pool Filter Replacement (Large)

Basic Info

Type of Cost: Replacement

Category: Mechanical

Condition: Unknown

Comments/Notes

Triton II Commercial

Useful Life

Last Activity Date: N/A

Est. Useful Life: 15y

Remaining Useful Life: 5y 6m

Next Activity Date: 01/01/2030

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$3,000.00
Total Quantity:	1 Ea
Total Current Cost:	\$3,000
Inflation Rate:	4.00%
Total Expenditures:	\$10,632

Powered by HomeRun IQ Page 100 of 204

42 - Pool Pump Replacement (2 HP)

Basic Info

Type of Cost: Replacement

Category: Mechanical

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 6y

Remaining Useful Life: 0y 6m

Next Activity Date: 01/01/2025

Financial Data

Estimate Date:	04/15/2024
Cost Per Ea:	\$2,200.00
Total Quantity:	2 Ea
Total Current Cost:	\$4,400
Inflation Rate:	4.00%
Total Expenditures:	\$38,692

Powered by HomeRun IQ Page 101 of 204

43 - Surveillance Camera Replacement

Basic Info

Type of Cost:	Replacement
Category:	Mechanical
Condition:	Unknown

Useful Life

Last Activity Date: N/A


Est. Useful Life: 4y

Remaining Useful Life: 0y 6m

Next Activity Date: 01/01/2025

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$429.00
Total Quantity:	10 Ea
Total Current Cost:	\$4,290
Inflation Rate:	4.00%
Total Expenditures:	\$65,878



Survellance Cameras

Powered by HomeRun IQ Page 102 of 204

45 - Surveillance Equipment Upgrade

Basic Info

Type of Cost: Improvement

Category: Mechanical

Condition: Unknown

Comments/Notes

Includes router, server, DVR, power supply

Useful Life

Last Activity Date: N/A

Est. Useful Life: 12y

Remaining Useful Life: 5y 6m

Next Activity Date: 01/01/2030

Financial Data

Estimate Date:	04/16/2024
Cost Per Lot:	\$6,000.00
Total Quantity:	1 Lot
Total Current Cost:	\$6,000
Inflation Rate:	4.00%
Total Expenditures:	\$39,207

Powered by HomeRun IQ Page 103 of 204

47 - Amenity Center Furniture Replacement

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 20y

Remaining Useful Life: 5y 6m

Next Activity Date: 01/01/2030

Financial Data

 Estimate Date:
 04/16/2024

 Cost Per Lot:
 \$10,560.00

 Total Quantity:
 1 Lot

 Total Current Cost:
 \$10,560

 Inflation Rate:
 4.00%

 Total Expenditures:
 \$42,639



Amenity Center Furniture

Powered by HomeRun IQ Page 104 of 204

48 - BBQ Grill Replacement

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Unknown

Comments/Notes

Jena air

Useful Life

Last Activity Date: N/A

Est. Useful Life: 15y

Remaining Useful Life: 0y 6m

Next Activity Date: 01/01/2025

Financial Data

Total Expenditures:

Estimate Date: 04/16/2024

Cost Per Ea: \$1,585.00

Total Quantity: 2 Ea

Total Current Cost: \$3,170

Inflation Rate: 4.00%

\$9,234

Powered by HomeRun IQ Page 105 of 204

49 - Decking Repairs - Creekway (Periodic)

Basic Info

Type of Cost: Repairs & Maintenance

Category: Amenities

Condition: Fair

Comments/Notes

Creekway - 10% of Total

Pool an Pool Decking

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 1y 6m

Next Activity Date: 01/01/2026

Financial Data

Estimate Date:	04/16/2024
Cost Per SF:	\$24.00
Total Quantity:	355 SF
Total Current Cost:	\$8,520
Inflation Rate:	4.00%
Total Expenditures:	\$43,048

Powered by HomeRun IQ Page 106 of 204

50 - Decking Repairs - Riverview (Periodic)

Basic Info

Type of Cost: Repairs & Maintenance

Category: Amenities

Condition: Fair

Comments/Notes

Riverview - 10% of Total

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 5y 6m

Next Activity Date: 01/01/2030

Financial Data

Estimate Date:	04/16/2024
Cost Per SF:	\$24.00
Total Quantity:	355 SF
Total Current Cost:	\$8,520
Inflation Rate:	4.00%
Total Expenditures:	\$50,360

Powered by HomeRun IQ Page 107 of 204

51 - Exercise Equipment - Elliptical Replacement

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Unknown

Comments/Notes

XE400

Exercise Equipment

Useful Life

Last Activity Date: N/A

Est. Useful Life: 14y

Remaining Useful Life: 1y 6m

Next Activity Date: 01/01/2026

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$5,940.00
Total Quantity:	2 Ea
Total Current Cost:	\$11,880
Inflation Rate:	4.00%
Total Expenditures:	\$73,632

Powered by HomeRun IQ Page 108 of 204

52 - Exercise Equipment - Spinner Replacement

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Fair

Comments/Notes

Precer

Useful Life

Last Activity Date: N/A
Est. Useful Life: 14y
Remaining Useful Life: 1y 6m

Next Activity Date: 01/01/2026

Financial Data

Estimate Date: 04/16/2024

Cost Per Ea: \$1,610.00

Total Quantity: 2 Ea

Total Current Cost: \$3,220

Inflation Rate: 4.00%

Total Expenditures: \$19,957

Powered by HomeRun IQ Page 109 of 204

53 - Exercise Equipment - Treadmill Replacement

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Unknown

Comments/Notes

True

Useful Life

Last Activity Date: N/A
Est. Useful Life: 14y

Remaining Useful Life: 1y 6m

Next Activity Date: 01/01/2026

Financial Data

Total Expenditures:

Estimate Date: 04/16/2024

Cost Per Ea: \$7,788.00

Total Quantity: 3 Ea

Total Current Cost: \$23,364

Inflation Rate: 4.00%

\$144,810

Powered by HomeRun IQ Page 110 of 204

54 - Exercise Equipment - Weight Machine Replacement

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Unknown

Comments/Notes

Apollo Tough Stuff 7000

Useful Life

Last Activity Date: N/A

Est. Useful Life: 14y

Remaining Useful Life: 1y 6m

Next Activity Date: 01/01/2026

Financial Data

Estimate Date: 04/16/2024

Cost Per Ea: \$5,940.00

Total Quantity: 1 Ea

Total Current Cost: \$5,940

Inflation Rate: 4.00%

Total Expenditures: \$36,816

Powered by HomeRun IQ Page 111 of 204

55 - Flat Screen Television Replacement

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 1y 6m

Next Activity Date: 01/01/2026

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$1,848.00
Total Quantity:	2 Ea
Total Current Cost:	\$3,696
Inflation Rate:	4.00%
Total Expenditures:	\$18,674

Powered by HomeRun IQ Page 112 of 204

56 - Mailbox Replacement

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 30y

Remaining Useful Life: 13y 6m

Next Activity Date: 01/01/2038

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$1,980.00
Total Quantity:	24 Ea
Total Current Cost:	\$47,520
Inflation Rate:	4.00%
Total Expenditures:	\$82,289

Powered by HomeRun IQ Page 113 of 204

57 - Park Bench Replacement

Basic Info

Type of Cost: Replacement
Category: Amenities
Condition: Fair

Park Bench

Useful Life

Last Activity Date: N/A

Est. Useful Life: 25y

Remaining Useful Life: 8y 6m

Next Activity Date: 01/01/2033

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$1,060.00
Total Quantity:	4 Ea
Total Current Cost:	\$4,240
Inflation Rate:	4.00%
Total Expenditures:	\$6,035

Powered by HomeRun IQ Page 114 of 204

59 - Pool Coping to Decking Joint, Both Pools (Deck-O-Seal)

Basic Info

Type of Cost: Repairs & Maintenance

Category: Amenities

Condition: Fair

Comments/Notes

Both pools

Useful Life

Last Activity Date: N/A

Est. Useful Life: 4y

Remaining Useful Life: 2y 6m

Next Activity Date: 01/01/2027

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$9.00
Total Quantity:	280 LF
Total Current Cost:	\$2,520
Inflation Rate:	4.00%
Total Expenditures:	\$33,355

Powered by HomeRun IQ Page 115 of 204

61 - Pool Coping/Tile Replacement - Creekway

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Good to Fair

Comments/Notes

Creekway

Useful Life

Last Activity Date: N/A

Est. Useful Life: 30y

Remaining Useful Life: 14y 6m

Next Activity Date: 01/01/2039

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$55.00
Total Quantity:	140 LF
Total Current Cost:	\$7,700
Inflation Rate:	4.00%
Total Expenditures:	\$13,867



Pool Coping/Tile

Powered by HomeRun IQ Page 116 of 204

62 - Pool Coping/Tile Replacement - Riverview

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Good to Fair

Comments/Notes

Riverview

Useful Life

Last Activity Date: N/A

Est. Useful Life: 30y

Remaining Useful Life: 25y 6m

Next Activity Date: 01/01/2050

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$55.00
Total Quantity:	140 LF
Total Current Cost:	\$7,700
Inflation Rate:	4.00%
Total Expenditures:	\$21,348

Powered by HomeRun IQ Page 117 of 204

63 - Pool Fencing - Clean/Prime/Paint (Periodic) - Creekway

Basic Info

Type of Cost: Repairs & Maintenance

Category: Amenities

Condition: Fair to Poor

Comments/Notes

Creekway

Useful Life

Last Activity Date: N/A

Est. Useful Life: 8y

Remaining Useful Life: 0y 6m

Next Activity Date: 01/01/2025

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$12.25
Total Quantity:	395 LF
Total Current Cost:	\$4,839
Inflation Rate:	4.00%
Total Expenditures:	\$34,244



Pool Fencing, Deterioration noted in isolated areas.

Powered by HomeRun IQ Page 118 of 204

64 - Pool Fencing - Clean/Prime/Paint (Periodic) - Riverview

Basic Info

Type of Cost: Repairs & Maintenance

Category: Amenities

Condition: Fair

Comments/Notes

Riverview

Useful Life

Last Activity Date: N/A
Est. Useful Life: 8y

Remaining Useful Life: 1y 6m

Next Activity Date: 01/01/2026

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$12.25
Total Quantity:	395 LF
Total Current Cost:	\$4,839
Inflation Rate:	4.00%
Total Expenditures:	\$35,614

Powered by HomeRun IQ Page 119 of 204

65 - Pool Fencing - Replacement

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Fair

Comments/Notes

Creekway

Pool Fence

Useful Life

Last Activity Date: N/A

Est. Useful Life: 40y

Remaining Useful Life: 24y 6m

Next Activity Date: 01/01/2049

Financial Data

Estimate Date:	04/16/2024
Cost Per LF:	\$80.00
Total Quantity:	790 LF
Total Current Cost:	\$63,200
Inflation Rate:	4.00%
Total Expenditures:	\$168,481

Powered by HomeRun IQ Page 120 of 204

67 - Pool Furniture Replacement

Basic Info

Type of Cost: Replacement
Category: Amenities
Condition: Fair

Pool Furniture

Useful Life

Last Activity Date: N/A

Est. Useful Life: 7y

Remaining Useful Life: 3y 6m

Next Activity Date: 01/01/2028

Financial Data

Estimate Date:	04/16/2024
Cost Per Lot:	\$12,000.00
Total Quantity:	1 Lot
Total Current Cost:	\$12,000
Inflation Rate:	4.00%
Total Expenditures:	\$88,812

Powered by HomeRun IQ Page 121 of 204

68 - Pool Re-Surface (Gunite) - Creekway

Basic Info

Type of Cost: Improvement

Category: Amenities

Condition: Unknown

Comments/Notes

Creekway

Useful Life

Last Activity Date: N/A
Est. Useful Life: 10y

Remaining Useful Life: 2y 6m

Next Activity Date: 01/01/2027

Financial Data

Estimate Date:	04/16/2024
Cost Per SF:	\$11.00
Total Quantity:	1,050 SF
Total Current Cost:	\$11,550
Inflation Rate:	4.00%
Total Expenditures:	\$60,692

Powered by HomeRun IQ Page 122 of 204

69 - Pool Re-Surface (Gunite) - Riverview

Basic Info

Type of Cost: Improvement

Category: Amenities

Condition: Unknown

Comments/Notes

Riverview

Useful Life

Last Activity Date: N/A

Est. Useful Life: 10y

Remaining Useful Life: 5y 6m

Next Activity Date: 01/01/2030

Financial Data

Estimate Date: 04/16/2024

Cost Per SF: \$8.58

Total Quantity: 1,050 SF

Total Current Cost: \$9,009

Inflation Rate: 4.00%

Total Expenditures: \$53,250

Powered by HomeRun IQ Page 123 of 204

70 - Wood Arbor Replacement

Basic Info

Type of Cost: Replacement

Category: Amenities

Condition: Fair

Useful Life

Last Activity Date: N/A

Est. Useful Life: 25y

Remaining Useful Life: 9y 6m

Next Activity Date: 01/01/2034

Financial Data

Estimate Date:	04/16/2024
Cost Per SF:	\$35.00
Total Quantity:	1,250 SF
Total Current Cost:	\$43,750
Inflation Rate:	4.00%
Total Expenditures:	\$64,761



Wood Arbor

Powered by HomeRun IQ Page 124 of 204

71 - Reserve Study Updates

Basic Info

Type of Cost: Improvement

Category: Other

Condition: Excellent

Useful Life

Last Activity Date: N/A

Est. Useful Life: 4y

Remaining Useful Life: 4y

Next Activity Date: 07/01/2028

Financial Data

Estimate Date:	04/16/2024
Cost Per Ea:	\$5,800.00
Total Quantity:	1 Ea
Total Current Cost:	\$5,800
Inflation Rate:	4.00%
Total Expenditures:	\$79,840

Powered by HomeRun IQ Page 125 of 204

72 - Contingency

Basic Info

Type of Cost: Improvement

Category: Other

Condition: Unknown

Useful Life

Last Activity Date: N/A

Est. Useful Life: 1y

Remaining Useful Life: 0y 6m

Next Activity Date: 01/01/2025

Financial Data

Estimate Date: 04/16/2024

Cost Per Ea: \$30,000.00

Total Quantity: 1 Ea

Total Current Cost: \$30,000

Inflation Rate: 4.00%

Total Expenditures: \$1,749,850

Powered by HomeRun IQ Page 126 of 204

Component Details

Brick Perimeter Fencing Repairs - Topped w/ Metal (Periodic)

Basic Info		Cost Data			
Type of Cost:	Repairs & Maintenance	Unit Cost (06/24/2024):	\$18.00		
Category:	Site	Total Qty to Maintain (100% of Total):	431 LF		
Est. Useful Life:	10:00	Total Current Cost:	\$7,758		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Brick Perimeter Fencing Repairs - Topped w/ Metal (Periodic)	N/A	N/A	01/01/2031	6:06	431 LF	\$7,758
Total					431 LF	\$7,758

Photos



Brick Perimeter Fence Topped with Metal Fence

Powered by HomeRun IQ Page 127 of 204

Brick Perimeter Fencing Repairs - 6' (Periodic)

Basic Info		Cost Data			
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$22.00		
Category:	Site	Total Qty to Maintain (100% of Total):	1,024 LF		
Est. Useful Life:	10:00	Total Current Cost:	\$22,528		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Brick Perimeter Fencing Repairs - 6' (Periodic)	N/A	N/A	01/01/2027	2:06	1,024 LF	\$22,528
Total					1,024 LF	\$22,528

Photos



Brick Perimeter Fence

Powered by HomeRun IQ Page 128 of 204

Lighting - Can Replacement

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$198.00		
Category:	Building Interior	Total Qty to Maintain (100% of Total):	60		
Est. Useful Life:	25:00	Total Current Cost:	\$11,880		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Brick Perimeter Fencing - Topped w/ Metal	N/A	N/A	01/01/2041	16:06	431 LF	\$77,580
Total					60	\$11,880



Brick Perimeter Fencing - Topped w/ Metal

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$180.00		
Category:	Site	Total Qty to Maintain (100% of Total):	431 LF		
Est. Useful Life:	30:00	Total Current Cost:	\$77,580		
Notes:	Topped with metal fence	Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Brick Perimeter Fencing - 6'	N/A	N/A	01/01/2041	16:06	1,024 LF	\$225,280
Total					431 LF	\$77,580

Photos

Powered by HomeRun IQ Page 130 of 204

Brick Perimeter Fencing - 6'

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$220.00		
Category:	Site	Total Qty to Maintain (100% of Total):	1,024 LF		
Est. Useful Life:	30:00	Total Current Cost:	\$225,280		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Concrete Parking Lot - Seal Joints, Stripe	N/A	N/A	01/01/2027	2:06	1 Lot	\$2,500
Total					1,024 LF	\$225,280

Photos



Concrete Parking Spaces

Powered by HomeRun IQ Page 131 of 204

Concrete Parking Lot - Seal Joints, Stripe

Basic Info		Cost Data		
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	;	
Category:	Site	Total Qty to Maintain (100% of Total):		

Category: Site Total Qty to Maintain (100% of Total): 1 Lot
Est. Useful Life: 5:00 Total Current Cost: \$2,500
Notes: Inflation Rate: 4.00%

\$2,500.00

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Concrete Walkway and Drive Repairs (Periodic)	N/A	N/A	01/01/2025	0:06	4,950 SF	\$89,100
Total					1 Lot	\$2,500

Photos



Concrete Walkway

Powered by HomeRun IQ Page 132 of 204



Concrete sidewalk trip hazards were observed in isolated locations

Powered by HomeRun IQ Page 133 of 204

Concrete Walkway and Drive Repairs (Periodic)

Basic Info		Cost Data				
Type of Cost:	Repairs & Maintenance	Unit Cost (07/01/2024):	\$18.00			
Category:	Site	Total Qty to Maintain (100% of Total):	4,950 SF			
Est. Useful Life:	7:00	Total Current Cost:	\$89,100			
Notes:	10% of total	Inflation Rate:	4.00%			

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Column Repairs	N/A	N/A	01/01/2026	1:06	14 Ea	\$3,920
Total					4,950 SF	\$89,100

Photos



Pilaster

Powered by HomeRun IQ Page 134 of 204

Column Repairs

Cost Data

Type of Cost:	Repairs & Maintenance	Unit Cost (07/01/2024):	\$280.00
Category:	Site	Total Qty to Maintain (100% of Total):	14 Ea
Est. Useful Life:	10:00	Total Current Cost:	\$3,920
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Retaining Wall Repairs (~ 4')	N/A	N/A	01/01/2031	6:06	1 Lot	\$24,000
Total					14 Ea	\$3,920

Photos



Retaining Wall

Powered by HomeRun IQ Page 135 of 204

Retaining Wall Repairs (~ 4')

Basic Info Cost Data

Type of Cost: Unit Cost (04/16/2024): Repairs & Maintenance \$24,000.00 Category: Total Qty to Maintain (100% of Total): 1 Lot Site Est. Useful Life: 10:00 **Total Current Cost:** \$24,000 4.00% Inflation Rate: Notes: \$8k done in '17

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Wood Perimeter Fencing Replacement	N/A	N/A	01/01/2033	8:06	992 LF	\$43,648
Total					1 Lot	\$24,000



Wood Perimeter Fencing Replacement

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$44.00		
Category:	Site	Total Qty to Maintain (100% of Total):	992 LF		
Est. Useful Life:	20:00	Total Current Cost:	\$43,648		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Wood Perimeter Fencing Stain	N/A	N/A	01/01/2027	2:06	992 LF	\$7,936
Total					992 LF	\$43,648



Wood Perimeter Fencing Stain

Basic Info		Cost Data				
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$8.00			
Category:	Site	Total Qty to Maintain (100% of Total):	992 LF			
Est. Useful Life:	5:00	Total Current Cost:	\$7,936			
Notes:		Inflation Rate:	4.00%			

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Wrought Iron Fencing - 6' Clean/Prime/Paint (Periodic)	N/A	N/A	01/01/2028	3:06	305 LF	\$3,736
Total					992 LF	\$7,936



Wrought Iron Fencing - 6' Clean/Prime/Paint (Periodic)

Basic Info		Cost Data			
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$12.25		
Category:	Site	Total Qty to Maintain (100% of Total):	305 LF		
Est. Useful Life:	10:00	Total Current Cost:	\$3,736		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Wrought Iron Atop Brick Fence- Clean/Prime/Paint (Periodic)	N/A	N/A	01/01/2028	3:06	431 LF	\$2,370
Total					305 LF	\$3,736



Wrought Iron Atop Brick Fence- Clean/Prime/Paint (Periodic)

Basic Info		Cost Data	
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$5.50
Category:	Site	Total Qty to Maintain (100% of Total):	431 LF
Est. Useful Life:	10:00	Total Current Cost:	\$2,370
Notes:	2ft on top of brick fence	Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Wrought Iron Fencing Replacement - 6'	N/A	N/A	01/01/2049	24:06	305 LF	\$22,875
Total					431 LF	\$2,370

Photos

Powered by HomeRun IQ Page 140 of 204

Wrought Iron Fencing Replacement - 6'

Basic Info		Cost Data	
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$75.00
Category:	Site	Total Qty to Maintain (100% of Total):	305 LF
Est. Useful Life:	40:00	Total Current Cost:	\$22,875
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Wrought Iron Fencing Replacement Atop Brick Fence	N/A	N/A	01/01/2049	24:06	431 LF	\$12,930
Total					305 LF	\$22,875



Wrought Iron Fencing Replacement Atop Brick Fence

Basic Info		Cost Data	
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$30.00
Category:	Site	Total Qty to Maintain (100% of Total):	431 LF
Est. Useful Life:	40:00	Total Current Cost:	\$12,930
Notes:	2ft on top of brick fence	Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Door Replacement	N/A	N/A	01/01/2034	9:06	9	\$8,316
Total					431 LF	\$12,930

Photos



Doors

Powered by HomeRun IQ Page 142 of 204

Door Replacement

Basic Info	Cost Data

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$924.00
Category:	Building Exterior	Total Qty to Maintain (100% of Total):	9
Est. Useful Life:	25:00	Total Current Cost:	\$8,316
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Garage Door - Paint	N/A	N/A	01/01/2025	0:06	255 Ea	\$117,810
Total					9	\$8,316

Photos



Garage Doors

Powered by HomeRun IQ Page 143 of 204

Garage Door - Paint

Basic Info	Cost Data
------------	-----------

Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$462.00
Category:	Building Exterior	Total Qty to Maintain (100% of Total):	255 Ea
Est. Useful Life:	8:00	Total Current Cost:	\$117,810
Notes:	Miracle Door pricing	Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Garage Door - Stain	N/A	N/A	01/01/2028	3:06	126 Ea	\$83,160
Total					255 Ea	\$117,810

Photos



Garage Doors and Exterior Components

Powered by HomeRun IQ Page 144 of 204

Garage Door - Stain

Includes armor guard

Basic Info		Cost Data			
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$660.00		
Category:	Building Exterior	Total Qty to Maintain (100% of Total):	126 Ea		
Est. Useful Life:	5:00	Total Current Cost:	\$83,160		
		Inflation Rate:	4.00%		

Items/Phases

Notes:

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Townhome Privacy Brick Fence, Repair	N/A	N/A	01/01/2026	1:06	2,028 LF	\$44,616
Total					126 Ea	\$83,160



Townhome Privacy Brick Fence, Repair

Basic Info		Cost Data			
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$22.00		
Category:	Building Exterior	Total Qty to Maintain (100% of Total):	2,028 LF		
Est. Useful Life:	10:00	Total Current Cost:	\$44,616		

Inflation Rate:

4.00%

Notes:

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Townhome - 4' Metal Fence Clean, Prime, Paint	N/A	N/A	01/01/2027	2:06	2,738 LF	\$24,642
Total					2,028 LF	\$44,616



Townhome - 4' Metal Fence Clean, Prime, Paint

Basic Info		Cost Data			
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$9.00		
Category:	Building Exterior	Total Qty to Maintain (100% of Total):	2,738 LF		
Est. Useful Life:	10:00	Total Current Cost:	\$24,642		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Townhome - Metal - 4' Fence Replacement	N/A	N/A	01/01/2049	24:06	2,738 LF	\$164,280
Total					2,738 LF	\$24,642



Townhome - Metal - 4' Fence Replacement

Basic Info		Cost Data				
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$60.00			
Category:	Building Exterior	Total Qty to Maintain (100% of Total):	2,738 LF			
Est. Useful Life:	40:00	Total Current Cost:	\$164,280			
Notes:		Inflation Rate:	4.00%			

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Townhome - Paint and Repair Exteriors	N/A	N/A	07/01/2024	0:00	381	\$457,200
Total					2,738 LF	\$164,280



Townhome - Paint and Repair Exteriors

Basic Info	Cost Data

Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$1,200.00
Category:	Building Exterior	Total Qty to Maintain (100% of Total):	381
Est. Useful Life:	8:00	Total Current Cost:	\$457,200
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Townhome - Roof and Gutter Replacement (33%)	N/A	N/A	01/01/2035	10:06	127 Ea	\$1,744,980
Total					381	\$457,200



Townhome - Roof and Gutter Replacement (33%)

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$13,740.00		
Category:	Building Exterior	Total Qty to Maintain (100% of Total):	127 Ea		
Est. Useful Life:	20:00	Total Current Cost:	\$1,744,980		
Notes:	Based on recent replacement cost	Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Townhome - Roof and Gutter Replacement (33%)	N/A	N/A	01/01/2038	13:06	127 Ea	\$1,744,980
Total					127 Ea	\$1,744,980

Photos

Powered by HomeRun IQ Page 150 of 204

Townhome - Roof and Gutter Replacement (33%)

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$13,740.00		
Category:	Building Exterior	Total Qty to Maintain (100% of Total):	127 Ea		
Est. Useful Life:	20:00	Total Current Cost:	\$1,744,980		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Townhome - Roof and Gutter Replacement (33%)	N/A	N/A	01/01/2041	16:06	127 Ea	\$1,744,980
Total					127 Ea	\$1,744,980



Townhome - Roof and Gutter Replacement (33%)

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$13,740.00		
Category:	Building Exterior	Total Qty to Maintain (100% of Total):	127 Ea		
Est. Useful Life:	20:00	Total Current Cost:	\$1,744,980		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Flooring Replacement - Carpet	N/A	N/A	01/01/2025	0:06	540 SF	\$3,510
Total					127 Ea	\$1,744,980



Flooring Replacement - Carpet

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$6.50		
Category:	Building Interior	Total Qty to Maintain (100% of Total):	540 SF		
Est. Useful Life:	15:00	Total Current Cost:	\$3,510		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Flooring Replacement - Exercise	N/A	N/A	01/01/2029	4:06	705 SF	\$6,345
Total					540 SF	\$3,510



Flooring Replacement - Exercise

Basic Info		Cost Data				
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$9.00			
Category:	Building Interior	Total Qty to Maintain (100% of Total):	705 SF			
Est. Useful Life:	20:00	Total Current Cost:	\$6,345			
Notes:		Inflation Rate:	4.00%			

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Interior Paint	N/A	N/A	01/01/2026	1:06	1 Lot	\$11,000
Total					705 SF	\$6,345



Interior Paint

Basic Info Cost Data

Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$11,000.00
Category:	Building Interior	Total Qty to Maintain (100% of Total):	1 Lot
Est. Useful Life:	8:00	Total Current Cost:	\$11,000
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Lighting - Can Replacement	N/A	N/A	01/01/2035	10:06	60	\$11,880
Total					1 Lot	\$11,000

Photos



Paint, Furniture, Floor, and Can Lights

Powered by HomeRun IQ Page 155 of 204

Restroom Fixture Replacement

Basic Info	Cost Data

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$7,260.00
Category:	Building Interior	Total Qty to Maintain (100% of Total):	1 Lot
Est. Useful Life:	25:00	Total Current Cost:	\$7,260
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Restroom Fixture Replacement	N/A	N/A	01/01/2035	10:06	1 Lot	\$7,260
Total					1 Lot	\$7,260



Restroom Partition Replacement

Basic Info		Cost Data	
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$990.00
Category:	Building Interior	Total Qty to Maintain (100% of Total):	3 Ea
Est. Useful Life:	30:00	Total Current Cost:	\$2,970
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Restroom Partition Replacement	N/A	N/A	01/01/2039	14:06	3 Ea	\$2,970
Total					3 Ea	\$2,970

Photos



Restroom Partition

Powered by HomeRun IQ Page 157 of 204

Access Control System Replacement

Basic Info		Cost Data	
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$5,000.00
Category:	Mechanical	Total Qty to Maintain (100% of Total):	1 Ea
Est. Useful Life:	15:00	Total Current Cost:	\$5,000
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Access Control System Replacement	N/A	N/A	07/01/2024	0:00	1 Ea	\$5,000
Total					1 Ea	\$5,000



Ceiling Fan Replacement

Basic Info		Cost Data				
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$350.00			
Category:	Mechanical	Total Qty to Maintain (100% of Total):	8 Ea			
Est. Useful Life:	16:00	Total Current Cost:	\$2,800			
Notes:		Inflation Rate:	4.00%			

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Ceiling Fan Replacement	N/A	N/A	01/01/2027	2:06	8 Ea	\$2,800
Total					8 Ea	\$2,800



Drinking Fountain Replacement

Basic Info	Cost Data

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$1,500.00
Category:	Mechanical	Total Qty to Maintain (100% of Total):	4 Ea
Est. Useful Life:	15:00	Total Current Cost:	\$6,000
	Ell	Inflation Rate:	4.00%
Notes:	Flkway		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Drinking Fountain Replacement	N/A	N/A	01/01/2025	0:06	4 Ea	\$6,000
Total					4 Ea	\$6,000

Photos



Drinking Fountain

Powered by HomeRun IQ Page 160 of 204

Electrical Panel Replacement

Basic Info	Cost Data

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$2,775.00
Category:	Mechanical	Total Qty to Maintain (100% of Total):	3 Ea
Est. Useful Life:	40:00	Total Current Cost:	\$8,325
		Inflation Rate:	4.00%
Notes:	Amenity center nools		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Electrical Panel Replacement	N/A	N/A	01/01/2049	24:06	3 Ea	\$8,325
Total					3 Ea	\$8,325



HVAC Replacement

Basic Info Cost Data

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$9,600.00
Category:	Mechanical	Total Qty to Maintain (100% of Total):	2 Ea
Est. Useful Life:	15:00	Total Current Cost:	\$19,200
	Aton 3ton	Inflation Rate:	4.00%


4 ton , 3 ton Notes:

Replaced in 2020

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
HVAC Replacement	N/A	N/A	01/01/2037	12:06	2 Ea	\$19,200
Total					2 Ea	\$19,200

Photos



HVAC

Powered by HomeRun IQ Page 162 of 204

Irrigation Controller Replacement

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$990.00		
Category:	Mechanical	Total Qty to Maintain (100% of Total):	22 Ea		
Est. Useful Life:	12:00	Total Current Cost:	\$21,780		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Irrigation Controller Replacement	N/A	N/A	07/01/2024	0:00	22 Ea	\$21,780
Total					22 Ea	\$21,780



Pond Equipment Replacement

Cost Data

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$12,000.00
Category:	Mechanical	Total Qty to Maintain (100% of Total):	1 Lot
Est. Useful Life:	15:00	Total Current Cost:	\$12,000
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Pond Equipment Replacement	N/A	N/A	01/01/2038	13:06	1 Lot	\$12,000
Total					1 Lot	\$12,000

Photos



Pond Equipment

Powered by HomeRun IQ Page 164 of 204


Pool Filter Replacement (Large)

Basic Info	Cost Data

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$3,000.00
Category:	Mechanical	Total Qty to Maintain (100% of Total):	1 Ea
Est. Useful Life:	15:00	Total Current Cost:	\$3,000
Makan	T-14 II O 1	Inflation Rate:	4.00%
Notes:	Triton II Commercial		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Pool Filter Replacement (Large)	N/A	N/A	01/01/2030	5:06	1 Ea	\$3,000
Total					1 Ea	\$3,000



Pool Pump Replacement (2 HP)

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/15/2024):	\$2,200.00		
Category:	Mechanical	Total Qty to Maintain (100% of Total):	2 Ea		
Est. Useful Life:	6:00	Total Current Cost:	\$4,400		

4.00% Inflation Rate: Notes:

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Pool Pump Replacement (2 HP)	N/A	N/A	01/01/2025	0:06	2 Ea	\$4,400
Total					2 Ea	\$4,400



Surveillance Camera Replacement

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$429.00		
Category:	Mechanical	Total Qty to Maintain (100% of Total):	10 Ea		
Est. Useful Life:	4:00	Total Current Cost:	\$4,290		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Surveillance Camera Replacement	N/A	N/A	01/01/2025	0:06	10 Ea	\$4,290
Total					10 Ea	\$4,290

Photos



Survellance Cameras

Powered by HomeRun IQ Page 167 of 204

Surveillance Equipment Upgrade

Basic Info		Cost Data	
Type of Cost:	Improvement	Unit Cost (04/16/2024):	\$6,000.00
Category:	Mechanical	Total Qty to Maintain (100% of Total):	1 Lot
Est. Useful	12:00	Total Current Cost:	\$6,000
Life:	12.00	Inflation Rate:	4.00%
Notes:	Includes router, server, DVR, power supply		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Surveillance Equipment Upgrade	N/A	N/A	01/01/2030	5:06	1 Lot	\$6,000
Total					1 Lot	\$6,000

Photos

Powered by HomeRun IQ Page 168 of 204

Amenity Center Furniture Replacement

Cost Data
ĺ

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$10,560.00
Category:	Amenities	Total Qty to Maintain (100% of Total):	1 Lot
Est. Useful Life:	20:00	Total Current Cost:	\$10,560
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Amenity Center Furniture Replacement	N/A	N/A	01/01/2030	5:06	1 Lot	\$10,560
Total					1 Lot	\$10,560

Photos



Amenity Center Furniture

Powered by HomeRun IQ Page 169 of 204

BBQ Grill Replacement

Basic Info		Cost Data	
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$1,585.00
Category:	Amenities	Total Qty to Maintain (100% of Total):	2 Ea
Est. Useful Life:	15:00	Total Current Cost:	\$3,170

Inflation Rate: 4.00% Notes: Jena air

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
BBQ Grill Replacement	N/A	N/A	01/01/2025	0:06	2 Ea	\$3,170
Total					2 Ea	\$3,170



Decking Repairs - Creekway (Periodic)

Basic Info		Cost Data	
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$24.00
Category:	Amenities	Total Qty to Maintain (100% of Total):	355 SF
Est. Useful Life:	10:00	Total Current Cost:	\$8,520
Notes:	Creekway - 10% of Total	Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Decking Repairs - Creekway (Periodic)	N/A	N/A	01/01/2026	1:06	355 SF	\$8,520
Total					355 SF	\$8,520

Photos



Pool an Pool Decking

Powered by HomeRun IQ Page 171 of 204

Decking Repairs - Riverview (Periodic)

Basic Info		Cost Data			
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$24.00		
Category:	Amenities	Total Qty to Maintain (100% of Total):	355 SF		
Est. Useful Life:	10:00	Total Current Cost:	\$8,520		
Notes:	Riverview - 10% of Total	Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Decking Repairs - Riverview (Periodic)	N/A	N/A	01/01/2030	5:06	355 SF	\$8,520
Total					355 SF	\$8,520



Exercise Equipment - Elliptical Replacement

Basic Info		Cost Data		
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$5,940.00	
Category:	Amenities	Total Qty to Maintain (100% of Total):	2 Ea	
Est. Useful Life:	14:00	Total Current Cost:	\$11,880	

Inflation Rate: 4.00% Notes: XE400

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Exercise Equipment - Elliptical Replacement	N/A	N/A	01/01/2026	1:06	2 Ea	\$11,880
Total					2 Ea	\$11,880

Photos



Exercise Equipment

Powered by HomeRun IQ Page 173 of 204

Exercise Equipment - Spinner Replacement

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$1,610.00		
Category:	Amenities	Total Qty to Maintain (100% of Total):	2 Ea		
Est. Useful Life:	14:00	Total Current Cost:	\$3,220		
		Inflation Rate:	4.00%		
Notes:	Precer				

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Exercise Equipment - Spinner Replacement	N/A	N/A	01/01/2026	1:06	2 Ea	\$3,220
Total					2 Ea	\$3,220

Photos

Powered by HomeRun IQ Page 174 of 204

Exercise Equipment - Treadmill Replacement

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$7,788.00		
Category:	Amenities	Total Qty to Maintain (100% of Total):	3 Ea		
Est. Useful Life:	14:00	Total Current Cost:	\$23,364		
		Inflation Rate:	4.00%		
Notes:	True				

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Exercise Equipment - Treadmill Replacement	N/A	N/A	01/01/2026	1:06	3 Ea	\$23,364
Total					3 Ea	\$23,364

Photos

Powered by HomeRun IQ Page 175 of 204

Exercise Equipment - Weight Machine Replacement

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$5,940.00		
Category:	Amenities	Total Qty to Maintain (100% of Total):	1 Ea		
Est. Useful Life:	14:00	Total Current Cost:	\$5,940		
Notes:	Apollo Tough Stuff 7000	Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity RUL (Years	s) Qty	Total Current Cost
Exercise Equipment - Weight Machine Replacement	N/A	N/A	01/01/2026 1:06	1 Ea	\$5,940
Total				1 Ea	\$5,940

Photos

Powered by HomeRun IQ Page 176 of 204

Flat Screen Television Replacement

Basic Info		Cost Data			
Type of Cost: Replacement		Unit Cost (04/16/2024):	\$1,848.00		
Category:	Amenities	Total Qty to Maintain (100% of Total):	2 Ea		
Est. Useful Life:	10:00	Total Current Cost:	\$3,696		
Notes:		Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Flat Screen Television Replacement	N/A	N/A	01/01/2026	1:06	2 Ea	\$3,696
Total					2 Ea	\$3,696



Mailbox Replacement

Basic Info	Cost Data

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$1,980.00
Category:	Amenities	Total Qty to Maintain (100% of Total):	24 Ea
Est. Useful Life:	30:00	Total Current Cost:	\$47,520
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Mailbox Replacement	N/A	N/A	01/01/2038	13:06	24 Ea	\$47,520
Total					24 Ea	\$47,520



Park Bench Replacement

Basic Info	Cost Data

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$1,060.00
Category:	Amenities	Total Qty to Maintain (100% of Total):	4 Ea
Est. Useful Life:	25:00	Total Current Cost:	\$4,240
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Park Bench Replacement	N/A	N/A	01/01/2033	8:06	4 Ea	\$4,240
Total					4 Ea	\$4,240

Photos



Park Bench

Powered by HomeRun IQ Page 179 of 204

Pool Coping to Decking Joint, Both Pools (Deck-O-Seal)

Basic Info		Cost Data			
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$9.00		
Category:	Amenities	Total Qty to Maintain (100% of Total):	280 LF		
Est. Useful Life:	4:00	Total Current Cost:	\$2,520		
Notes:	Both pools	Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Pool Coping to Decking Joint, Both Pools (Deck-O- Seal)	N/A	N/A	01/01/2027	2:06	280 LF	\$2,520
Total					280 LF	\$2,520

Photos

Powered by HomeRun IQ Page 180 of 204

Pool Coping/Tile Replacement - Creekway

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$55.00		
Category:	Amenities	Total Qty to Maintain (100% of Total):	140 LF		
Est. Useful Life:	30:00	Total Current Cost:	\$7,700		
Notes:	Creekway	Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Pool Coping/Tile Replacement - Creekway	N/A	N/A	01/01/2039	14:06	140 LF	\$7,700
Total					140 LF	\$7,700

Photos



Pool Coping/Tile

Powered by HomeRun IQ Page 181 of 204

Pool Coping/Tile Replacement - Riverview

Basic Info		Cost Data	
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$55.00
Category:	Amenities	Total Qty to Maintain (100% of Total):	140 LF
Est. Useful Life:	30:00	Total Current Cost:	\$7,700
Notes:	Riverview	Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Pool Coping/Tile Replacement - Riverview	N/A	N/A	01/01/2050	25:06	140 LF	\$7,700
Total					140 LF	\$7,700

Photos

Powered by HomeRun IQ Page 182 of 204

Pool Fencing - Clean/Prime/Paint (Periodic) - Creekway

Basic Info		Cost Data				
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$12.25			
Category:	Amenities	Total Qty to Maintain (100% of Total):	395 LF			
Est. Useful Life:	8:00	Total Current Cost:	\$4,839			
Notes:	Creekway	Inflation Rate:	4.00%			

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity RUI	(Years) Qty	Total Current Cost
Pool Fencing - Clean/ Prime/Paint (Periodic) - Creekway	N/A	N/A	01/01/2025	0:06 395 LF	\$4,839
Total				395 LF	\$4,839

Photos



Pool Fencing, Deterioration noted in isolated areas.

Powered by HomeRun IQ Page 183 of 204

Pool Fencing - Clean/Prime/Paint (Periodic) - Riverview

Basic Info		Cost Data			
Type of Cost:	Repairs & Maintenance	Unit Cost (04/16/2024):	\$12.25		
Category:	Amenities	Total Qty to Maintain (100% of Total):	395 LF		
Est. Useful Life:	8:00	Total Current Cost:	\$4,839		
Notes:	Riverview	Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity RUL (Years	s) Qty	Total Current Cost
Pool Fencing - Clean/ Prime/Paint (Periodic) - Riverview	N/A	N/A	01/01/2026 1:06	395 LF	\$4,839
Total				395 LF	\$4,839

Photos

Powered by HomeRun IQ Page 184 of 204

Pool Fencing - Replacement

Basic Info	Cost Data
------------	-----------

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$80.00
Category:	Amenities	Total Qty to Maintain (100% of Total):	790 LF
Est. Useful Life:	40:00	Total Current Cost:	\$63,200
		Inflation Rate:	4.00%
Notes:	Creekway		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Pool Fencing - Replacement	N/A	N/A	01/01/2049	24:06	790 LF	\$63,200
Total					790 LF	\$63,200

Photos



Pool Fence

Powered by HomeRun IQ Page 185 of 204

Pool Furniture Replacement

Basic Info	Cost Data
Dasic IIIIO	COSI

Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$12,000.00
Category:	Amenities	Total Qty to Maintain (100% of Total):	1 Lot
Est. Useful Life:	7:00	Total Current Cost:	\$12,000
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Pool Furniture Replacement	N/A	N/A	01/01/2028	3:06	1 Lot	\$12,000
Total					1 Lot	\$12,000

Photos



Pool Furniture

Powered by HomeRun IQ Page 186 of 204

Pool Re-Surface (Gunite) - Creekway

Basic Info		Cost Data			
Type of Cost:	Improvement	Unit Cost (04/16/2024):	\$11.00		
Category:	Amenities	Total Qty to Maintain (100% of Total):	1,050 SF		
Est. Useful Life:	10:00	Total Current Cost:	\$11,550		
Notes:	Creekway	Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Pool Re-Surface (Gunite) - Creekway	N/A	N/A	01/01/2027	2:06	1,050 SF	\$11,550
Total					1,050 SF	\$11,550

Photos

Powered by HomeRun IQ Page 187 of 204

Pool Re-Surface (Gunite) - Riverview

Basic Info		Cost Data			
Type of Cost:	Improvement	Unit Cost (04/16/2024):	\$8.58		
Category:	Amenities	Total Qty to Maintain (100% of Total):	1,050 SF		
Est. Useful Life:	10:00	Total Current Cost:	\$9,009		
Notes:	Riverview	Inflation Rate:	4.00%		

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Pool Re-Surface (Gunite) - Riverview	N/A	N/A	01/01/2030	5:06	1,050 SF	\$9,009
Total					1,050 SF	\$9,009

Photos

Powered by HomeRun IQ Page 188 of 204

Wood Arbor Replacement

Basic Info		Cost Data			
Type of Cost:	Replacement	Unit Cost (04/16/2024):	\$35.00		
Category:	Amenities	Total Qty to Maintain (100% of Total):	1,250 SF		
Est. Useful Life:	25:00	Total Current Cost:	\$43,750		

Inflation Rate:

4.00%

Notes:

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Wood Arbor Replacement	N/A	N/A	01/01/2034	9:06	1,250 SF	\$43,750
Total					1,250 SF	\$43,750

Photos



Wood Arbor

Powered by HomeRun IQ Page 189 of 204

Reserve Study Updates

Basic Info Cost Data

Type of Cost:	Improvement	Unit Cost (04/16/2024):	\$5,800.00
Category:	Other	Total Qty to Maintain (100% of Total):	1 Ea
Est. Useful Life:	4:00	Total Current Cost:	\$5,800
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Reserve Study Updates	N/A	N/A	07/01/2028	4:00	1 Ea	\$5,800
Total					1 Ea	\$5,800

Photos



Contingency

Basic Info	Cost Data
------------	-----------

Type of Cost:	Improvement	Unit Cost (04/16/2024):	\$30,000.00
Category:	Other	Total Qty to Maintain (100% of Total):	1 Ea
Est. Useful Life:	1:00	Total Current Cost:	\$30,000
Notes:		Inflation Rate:	4.00%

Items/Phases

Item/Phase	Last Activity Date	Useful Life (UL)	Next Activity Date	RUL (Years)	Qty	Total Current Cost
Contingency	N/A	N/A	01/01/2025	0:06	1 Ea	\$30,000
Total					1 Ea	\$30,000

Photos





Powered by HomeRun IQ Page 192 of 204

APPENDIX C REFERENCE DOCUMENTS

Powered by HomeRun IQ Page 193 of 204

Reserve Specialist® (RS®) Designation

NATIONAL RESERVE STUDY STANDARDS

General Information About Reserve Studies

One of the primary responsibilities of the board of directors of a community association is to protect, maintain, and enhance the assets of the association. To accomplish this objective, associations must develop multi-year plans to help them anticipate and responsibly prepare for the timely repair and replacement of common area components such as roofs, roads, mechanical equipment, and other portions of the community's common elements.

Originally published in 1998, the National Reserve Study Standards provide a consistent set of terminology, calculations, and expectations so reserve study providers and those they serve together can build a successful future for millions of community association homeowners across the country.

A reserve study is made up of two parts, the **physical analysis** and the **financial analysis**. The physical analysis includes the component inventory, condition assessment, and life and valuation estimates. The component inventory should be relatively stable from year to year, while the condition assessment and life and valuation estimate change from year to year.

The financial analysis is made up of an analysis of the client's current reserve fund status (measured in cash or as percent funded) and a recommendation for an appropriate reserve contribution rate (a funding plan).

Physical analysis

- · Component inventory
- Condition assessment
- Life and valuation estimates

Financial analysis

- Fund Status
- Funding Plan

Powered by HomeRun IQ Page 194 of 204

Levels of Service

The following three categories describe the various types of reserve studies, from exhaustive to minimal.

I. Full.

A reserve study in which the following five reserve study tasks are performed:

- Component inventory
- Condition assessment (based upon on-site visual observations)
- · Life and valuation estimates
- Fund Status
- Funding Plan

II. Update, With Site Visit/On-Site Review.

A reserve study update in which the following five reserve study tasks are performed:

- · Component inventory (verification only, not quantification)
- Condition assessment (based upon on-site visual observations)
- Life and valuation estimates
- Fund Status
- Funding Plan

III. Update, No-Site-Visit/Off Site Review.

A reserve study update with no on-site visual observations in which the following three reserve study tasks are performed:

- · Life and valuation estimates
- Fund Status
- Funding Plan

IV. Preliminary, Community Not Yet Constructed.

A reserve study prepared before construction that is generally used for budget estimates. It is based on design documents such as the architectural and engineering plans. The following three tasks are performed to prepare this type of study.

- Component inventory
- · Life and valuation estimates
- Funding Plan

Powered by HomeRun IQ Page 195 of 204

Terms and Definitions

CAPITAL IMPROVEMENTS: Additions to the association's common elements that previously did not exist. While these components should be added to the reserve study for future replacement, the cost of construction should not be taken from the reserve fund. CASH FLOW METHOD: A method of developing a reserve funding plan where contributions to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different reserve funding plans are tested against the anticipated schedule of reserve expenses until the desired funding goal is achieved.

COMPONENT: The individual line items in the reserve study developed or updated in the physical analysis. These elements form the building blocks for the reserve study. These components comprise the common elements of the community and typically are: 1. association responsibility, 2. with limited useful life expectancies, 3. predictable remaining useful life expectancies, and 4. above a minimum threshold cost. It should be noted that in certain jurisdictions there may be statutory requirements for including components or groups of components in the reserve study.

COMPONENT INVENTORY: The task of selecting and quantifying reserve components. This task can be accomplished through on-site visual observations, review of association design and organizational documents, review of association precedents, and discussion with appropriate representative(s) of the association.

COMPONENT METHOD: A method of developing a reserve funding plan where the total contribution is based on the sum of contributions for the individual components.

CONDITION ASSESSMENT: The task of evaluating the current condition of the component based on observed or reported characteristics.

EFFECTIVE AGE: The difference between useful life and remaining useful life. Not always equivalent to chronological age, since some components age irregularly. Used primarily in computations.

FINANCIAL ANALYSIS: The portion of a reserve study where the current status of the reserves (measured as cash or percent funded) and a recommended reserve contribution rate (funding plan) are derived, and the projected reserve income and expense over a period of time are presented. The financial analysis is one of the two parts of a reserve study.

FULLY FUNDED: 100 percent funded. When the actual (or projected) reserve balance is equal to the fully funded balance.

FULLY FUNDED BALANCE (FFB): An indicator against which the actual (or projected) reserve balance can be compared. The reserve balance that is in direct proportion to the fraction of life "used up" of the current repair or replacement cost. This number is calculated for each component, and then summed for an association total.

FFB = Current Cost X Effective Age/Useful Life

Example: For a component with a \$10,000 current replacement cost, a 10-year useful life and effective age of 4 years the fully funded balance would be \$4,000.

FUND STATUS: The status of the reserve fund reported in terms of cash or percent funded.

FUNDING GOALS: Independent of methodology used, the following represent the basic categories of funding plan goals. They are presented in order of greatest risk to least risk. Risk includes, but is not limited to, cash problems, special assessments, and deferred maintenance.

Baseline Funding: Establishing a reserve funding goal of allowing the reserve cash balance to never be below zero during the cash flow projection. This is the funding goal with the greatest risk due to the

Powered by HomeRun IQ Page 196 of 204

variabilities encountered in the timing of component replacements and repair and replacement costs.

Threshold Funding: Establishing a reserve funding goal of keeping the reserve balance above a specified dollar or percent funded amount. Depending on the threshold selected, this funding goal may be weaker or stronger than "Fully Funded" with respective higher risk or less risk of cash problems.

Full Funding: Setting a reserve funding goal to attain and maintain reserves at or near 100 percent funded. This is the most conservative funding goal.

It should be noted that in certain jurisdictions there may be statutory funding requirements that would dictate the minimum requirements for funding.

FUNDING PLAN: An association's plan to provide income to a reserve fund to offset anticipated expenditures from that fund. The plan must be a minimum of twenty (20) years.

FUNDING PRINCIPLES: The reserve provider must provide a funding plan addressing these principles.

- Sufficient funds when required
- · Stable contribution rate over the years
- · Equitable contribution rate over the years
- Fiscally responsible

LIFE AND VALUATION ESTIMATES: The task of estimating useful life, remaining useful life, and current repair or replacement costs for the reserve components.

PERCENT FUNDED: The ratio, at a particular point in time related to the fiscal year end, of the actual (or projected) reserve balance to the fully funded balance, expressed as a percentage. While percent funded is an indicator of an association's reserve fund size, it should be viewed in the context of how it is changing due to the association's reserve funding plan in light of the association's risk tolerance.

PHYSICAL ANALYSIS: The portion of the reserve study where the component inventory, condition assessment, and life and valuation estimate tasks are performed. This represents one of the two parts of the reserve study.

REMAINING USEFUL LIFE (RUL): Also referred to as "remaining life" (RL). The estimated time, in years, that a reserve component can be expected to serve its intended function. Projects expected to occur in the initial year have zero remaining useful life.

REPLACEMENT COST: The cost to replace, repair, or restore the component to its original functional condition during that particular year, including all related expenses (including but not limited to shipping, engineering and design, permits, installation, disposal, etc.).

RESERVE BALANCE: Actual or projected funds, as of a particular point in time that the association has identified, to defray the future repair or replacement cost of those major components that the association is obligated to maintain or replace. Also known as reserves, reserve accounts, cash reserves. Based on information provided and not audited.

RESERVE PROVIDER: An individual who prepares reserve studies. In many instances the reserve provider will possess a specialized designation such as the Reserve Specialist (RS) designation provided by Community Associations Institute (CAI). This designation indicates that the provider has shown the necessary skills to perform a reserve study that conforms to these standards.

RESERVE PROVIDER FIRM: A company that prepares reserve studies as one of its primary business activities.

RESERVE STUDY: A budget planning tool which identifies the components that the association is responsible to maintain or replace, the current status of the reserve fund, and a stable and equitable funding plan to offset the

Powered by HomeRun IQ Page 197 of 204

anticipated future major common area expenditures. The reserve study consists of two parts: the physical analysis and the financial analysis.

RESPONSIBLE CHARGE: A Reserve Specialist (RS) in responsible charge of a reserve study shall render regular and effective supervision to those individuals performing services that directly and materially affect the quality and competence of services rendered by the Reserve Specialist. A Reserve Specialist shall maintain such records as are reasonably necessary to establish that the Reserve Specialist exercised regular and effective supervision of a reserve study of which he or she was in responsible charge. A Reserve Specialist engaged in any of the following acts or practices shall be deemed not to have rendered the regular and effective supervision required herein:

- 1. The regular and continuous absence from principal office premises from which professional services are rendered; except for performance of field work or presence in a field office maintained exclusively for a specific project;
- 2. The failure to personally inspect or review the work of subordinates where necessary and appropriate;
- 3. The rendering of a limited, cursory or perfunctory review of plans or projects in lieu of an appropriate detailed review; and
- 4. The failure to personally be available on a reasonable basis or with adequate advance notice for consultation and inspection where circumstances require personal availability.

SPECIAL ASSESSMENT: A temporary assessment levied on the members of an association in addition to regular assessments. Note that special assessments are often regulated by governing documents or local statutes.

USEFUL LIFE (UL): The estimated time, in years, that a reserve component can be expected to serve its intended function if properly constructed in its present application or installation.



Reserve Study Contents

The following is a list of the minimum contents to be included in the Reserve Study.

- 1. A summary of the association's number of units, physical description and reserve fund financial condition.
- 2. A projection of reserve starting balance, recommended reserve contributions, projected reserve expenses, and projected ending reserve fund balance for a minimum of 20 years.
- 3. A tabular listing of the component inventory, component quantity or identifying descriptions, useful life, remaining useful life and current replacement cost.
- 4. A description of methods and objectives utilized in computing the Fund Status and development of the Funding Plan.
- 5. Source(s) utilized to obtain component repair or replacement cost estimates.
- 6. A description of the level of service by which the Reserve Study was prepared.
- 7. Fiscal year for which the Reserve Study is prepared.

Disclosures

The following are the minimum disclosures to be included in the Reserve Study:

- 1. General: Description of the other involvement(s) with the association, which could result in actual or perceived conflicts of interest.
- 2. **Physical Analysis**: Description of how thorough the on-site observations were performed: representative samplings vs, all common areas, destructive testing or not, field measurements vs. drawing take-offs, etc.
- 3. Financial Analysis: Description of assumptions utilized for interest and inflation, tax and other outside factors.
- 4. Personnel Credentials: State or organizational licenses or credentials carried by the individual responsible for Reserve Study preparation or oversight.
- 5. Update Reports: Disclosure of how the current work is reliant on the validity of prior Reserve Studies.
- 6. Completeness: Material issues which, if not disclosed, would cause a distortion of the association's situation.
- 7. Reliance on Client Data: Information provided by the official representative of the association regarding financial, physical, quantity, or historical issues will be deemed reliable by the consultant and assembled for the association's use, not for the purpose of performing an audit, quality/forensic analysis, or background checks of historical records.
- 8. Reserve Balance: The actual or projected total presented in the Reserve Study is based upon information provided and was not audited.
- 9. **Component Quantities**: For update with site visit and update no site visit levels of service, the client is considered to have deemed previously developed component quantities as accurate and reliable.
- 10. Reserve Projects: Information provided about reserve projects will be considered reliable. Any on-site inspection should not be considered a project audit or quality inspection.

Powered by HomeRun IQ Page 199 of 204

TERMS OF REFERENCE RESERVE STUDY			
Association	The unit owners' association. May be referred to with different terminology in legal covenants of incorporation.		
Board	Elected officers of the Association with fiduciary responsibility for the community's common holdings. May be referred to with different terminology in legal covenants of incorporation.		
Owner	Individual Unit owner, a Member or the Association		
Property Manager	Professional organization through which the Board delegates responsibilities for operations and maintenance of the community.		
Excellent	Component or system is in "as new" condition, requiring no rehabilitation and should perform in accordance with expected performance.		
Good	Component or system is sound and performing its function, although it may show signs of normal wear and tear. Some minor rehabilitation work may be required.		
Fair	Component or system falls into one or more of the following categories: a) Workmanship not in compliance with commonly accepted standards, b) Evidence of previous repairs not in compliance with commonly accepted practice, c) Component or system is obsolete, d) Component or system approaching end of expected performance. Repair or replacement is required to prevent further deterioration or to prolong expected life.		
Poor	Component or system has either failed or cannot be relied upon to continue performing its original function as a result of having exceeded its expected performance, excessive deferred maintenance, or state of disrepair. Present condition could contribute to or cause the deterioration of other adjoining elements or systems. Repair or replacement is required.		
Basis of Comparison	Ratings are determined by comparison to other buildings of similar age and construction type.		
Left, Right, Front, Rear	Directions are taken from the viewpoint of an observer standing at the property frontage and facing it. Or, for a building within a campus setting, the viewpoint of an observer standing in front of the principal entrance and facing it.		
Current Deficiency Immediate Expense	We will note any observed or reported physical condition which requires immediate action to correct an existing or potential safety hazard, an enforceable building code violation, or the poor or deteriorated condition of a critical element or system. Also, to address any conditions which, if left "as is", would likely result in the failure of a critical element or system. Such items will be noted in our report even if they do not require a reserve expenditure.		
Short-Term Reserve Expenditures	Correction of physical deficiencies including deferred maintenance, which may not warrant immediate attention, but require repairs or replacements which should be undertaken on a priority basis, taking precedence over preventive maintenance work within a one-year time frame. Included are physical deficiencies resulting from improper design, faulty installation, and/or substandard quality of original systems or materials. Components or systems that have exceeded their expected useful life and require repair or replacement within a one-year time frame are also included. Observed minor issues which would typically be addressed as normal operations & maintenance work may not be noted in the report.		
Long-term Reserve expenditures	Non-routine repairs, replacements or planned improvements that will require significant expenditure during the study period. Included are items that will reach the end of their estimated useful life or which, in the opinion of the engineer, will require such expense during that time. If saving for longer- term expenditures is desired, then allowances or contingencies for such items may also be included. Observed minor issues which would typically be addressed as normal operations & maintenance work may not be noted in the report.		

Powered by HomeRun IQ Page 200 of 204

Expected Useful Life (EUL)	As components age, they wear and deteriorate at varying rates, depending on their service and exposure. Although it is an inexact science, various financial underwriters, data services and trade organizations publish guidance regarding the EULs of typical building materials and operating systems. For short-lived components, their EUL is used as the frequency between periodic repairs or replacements. Some systems' economic life may be shortened because improved equipment or materials has become available which is less costly to operate or maintain.
Remaining Useful Life (RUL)	The simple equation for determining remaining useful life before repair or replacement is: EUL – Age = RUL However, based on our evaluation of a component and our professional judgment, we may assign a shorter or longer RUL to actual items being considered.



Powered by HomeRun IQ Page 201 of 204

	BUILDING SYSTEMS AND COMPONENTS COMMON ABBREVIATIONS AND ACRONYMS				
ACM	Asbestos Containing Material	нw	Hot Water		
ACT	Acoustic Ceiling Tile	нwн	Hot Water Heater (domestic)		
ADA	Americans with Disabilities Act	IBC	International Building Code		
AHU	Air Handling Unit	IRC	International Residential Code		
ASHRAE	American Society of Heating, Refrigeration and Air- Conditioning Engineers	KVA	Kilovolt-Ampere		
ASTM	American Society for Testing and Materials	LF	Lineal Foot		
BOCA	Building Officials Code Administrators International	MSL	Mean Sea Level		
BTU	British Thermal Unit	NEC	National Electric Code		
BTUH	British Thermal Unit / Hour	NFPA	National Fire Protection Association		
CFM	Cubic Foot / Minute	МВН	Thousand British Thermal Units / Hour		
CI	Cast Iron (piping)	MDP	Main Distribution Panel (electric power)		
CIP	Cast In Place (concrete)	0&M	Operations & Maintenance		
СМИ	Concrete Masonry Unit (block)	OSB	Oriented Strand Board (sheathing or decking)		
CPVC	Chlorinated Poly Vinyl Chloride (piping)	PCA	Property Condition Assessment		
cw	Cold Water	PCR	Property Condition Report		
DI	Ductile Iron (piping)	PE	Licensed Professional Engineer		
EIFS	Exterior Insulating and Finishing System	PVC	Poly Vinyl Chloride (piping and siding)		
EPDM	Ethylene Propylene Diene Monomer	PTAC	Packaged Terminal Air Conditioning Unit		
EUL	Expected Useful Life	ROM	Rough Order of Magnitude		
FCU	Fan Coil Unit	RUL	Remaining Useful Life		
FEMA	Federal Emergency Management Agency	RTU	Roof Top Unit		
FFE	Furniture, Fixtures and Equipment	SF	Square Foot		
FHA	Forced Hot Air	SOG	Slab on Grade (concrete basement or ground floor)		
FHAA	Fair Housing Act and Amendments	SQ	100 Square Feet		
FHW	Forced Hot Water	SY	Square Yard		
FIRM	Flood Insurance Rate Map	UBC	Uniform Building Code		
FOIA	Freedom of Information Act	UL	Underwriters Laboratories		
GFI	Ground Fault Interruption (circuit breaker)	VAC	Volts Alternating Current		
GWB	Gypsum Wall Board (drywall or sheetrock)	VAV	Variable Air Volume box		
	Hama Dun IO		Daga 202 of 204		

Powered by HomeRun IQ Page 202 of 204

HID	High Intensity Discharge (lamp, lighting fixture)	VCT	Vinyl Composition Tile
HVAC	Heating Ventilation and Air Conditioning	vwc	Vinyl Wall Covering



Powered by HomeRun IQ Page 203 of 204

Reserve Study Contents

The following is a list of the minimum contents to be included in the Reserve Study.

- 1. A summary of the association's number of units, physical description and reserve fund financial condition.
- 2. A projection of reserve starting balance, recommended reserve contributions, projected reserve expenses, and projected ending reserve fund balance for a minimum of 20 years.
- 3. A tabular listing of the component inventory, component quantity or identifying descriptions, useful life, remaining useful life and current replacement cost.
- 4. A description of methods and objectives utilized in computing the Fund Status and development of the Funding Plan.
- 5. Source(s) utilized to obtain component repair or replacement cost estimates.
- 6. A description of the level of service by which the Reserve Study was prepared.
- 7. Fiscal year for which the Reserve Study is prepared.

Disclosures

The following are the minimum disclosures to be included in the Reserve Study:

- 1. **General**: Description of the other involvement(s) with the association, which could result in actual or perceived conflicts of interest.
- 2. **Physical Analysis**: Description of how thorough the on-site observations were performed: representative samplings vs, all common areas, destructive testing or not, field measurements drawing take-offs, etc.
- Financial Analysis: Description of assumptions utilized for interest and inflation, tax and other outside factors.
- 4. **Personnel Credentials**: State or organizational licenses or credentials carried by the individual responsible for Reserve Study preparation or oversight.
- 5. Update Reports: Disclosure of how the current work is reliant on the validity of prior Reserve Studies.
- 6. **Completeness**: Material issues which, if not disclosed, would cause a distortion of the association's situation.
- 7. Reliance on Client Data: Information provided by the official representative of the association regarding financial, physical, quantity, or historical issues will be deemed reliable by the consultant and assembled for the association's use, not for the purpose of performing an audit, quality/forensic analysis, or background checks of historical records.
- 8. **Reserve Balance:** The actual or projected total presented in the Reserve Study is based upon information provided and was not audited.
- 9. **Component Quantities**: For update with site visit and update no site visit levels of service, the client is considered to have deemed previously developed component quantities as accurate and reliable.
- 10. **Reserve Projects**: Information provided about reserve projects will be considered Any on-site inspection should not be considered a project audit or quality inspection.

Powered by HomeRun IQ Page 204 of 204